



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

| | | | |
|-----------------|-------------------|---------------------|--------------------------|
| Client | MFC Auction House | Inspection Location | MFC |
| Requested Date | 12/06/2025 | | M57 Pretoria Road - 1619 |
| Inspection Date | 12/06/2025 | | Kempton Park - GT |

Vehicle Data

| | | | |
|-----------------|-------------------|-------------------------|--------------|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | |
| Manufacturer | RENAULT | Registration Number | JN82MYGP |
| Model | SANDERO | Register Number | |
| VIN | VF15SRLA461993881 | Date Of First Licensing | |
| Engine Number | | Last COR | |
| Doors | 5 | License Expiry Date | 31/10/2025 |
| Color | WHITE | Power / Displacement | |
| Year Model | | Paint Finish | TWO COAT UNI |
| Km Reading | 105,399 KM | Fuel | PETROL |
| Cab / Body Type | HATCHBACK | Transmission | MANUAL |

Vehicle Options & Accessories**Items****VEHICLE INSPECTION**

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



| Damage | Repair Way |
|--|------------|
| Engine Oil Leak | Repair |
| Front Bumper Damaged | Repair |
| Front Fender Left Damaged | Repair |
| Front Fender Right Damaged | Repair |
| Rear Fender Left Damaged | Repair |
| Rear Fender Right Damaged | Repair |
| Door Front Left Damaged | Repair |
| Door Front Right Damaged | Repair |
| Door Rear Left Damaged | Repair |
| Door Rear Right Damaged | Repair |
| Boot Lid / Hatch door Damaged | Repair |
| Rear bumper Damaged | Repair |
| Parking Brake Performance Left / Right Difference out of legal range | Repair |
| Tyre Front Left Worn | Repair |
| Tyre Front Right Worn | Repair |
| Tyre Rear Left Worn | Repair |
| Gearbox Oil Leak | Repair |

Brakes

Brake Test Results

| | Left | Right | Axe Weight [KG] | Deceleration [m/s ²] |
|---------------------|--------------------|--------------------|-----------------|----------------------------------|
| | Braking Force [KN] | Braking Force [KN] | | |
| Front | 2.48 | 2.61 | - | |
| Rear | 1.74 | 2.16 | - | |
| Emergency / Parking | 0.1 | 1.69 | - | |

Tyres and Rims

Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|--------|-------|-----------------|------------------|
| Front Left | 185/65R15 | 88H | Kumho | Radial | V | 3121 | 0 mm |
| Front Right | 185/65R15 | 88H | Kumho | Radial | V | 2021 | 0 mm |
| Rear Left | 185/65R15 | 88H | Kumho | Radial | V | 5121 | 0 mm |
| Rear Right | 185/65R15 | 88H | Kumho | Radial | V | 3121 | 1 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881

**CONDITION REPORT**

Report No:
2016911273
DATE
12/06/2025

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: battery loose.
Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: VF15SRLA461993881




CONDITION REPORT




Report No:
2016911273
DATE
12/06/2025




Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT




Report No:
2016911273
DATE
12/06/2025



Water level



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Front Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



Door Front Right



Door Rear Right



Tyre Rear Left



Tyre Front Left



Tyre Front Right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881



CONDITION REPORT



Report No:
2016911273
DATE
12/06/2025



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRLA461993881