



## CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 30/04/2024        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 30/04/2024        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |                   |
|-----------------|-------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | AUDI              | Registration Number     | HW73GRGP          |
| Model           | A3 TFSI           | Register Number         |                   |
| VIN             | WAUZZZ8V1KA024481 | Date Of First Licensing |                   |
| Engine Number   |                   | Last COR                |                   |
| Doors           | 5                 | License Expiry Date     | 30/04/2024        |
| Color           | GREY              | Power / Displacement    |                   |
| Year Model      |                   | Paint Finish            | TWO COAT UNI      |
| Km Reading      | 99,540 KM         | Fuel                    | PETROL            |
| Cab / Body Type | HATCHBACK         | Transmission            | AUTOMATIC         |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

| Damage   | Repair Way |
|--|------------|
| Engine Oil Sweat                                       | Repair     |
| Fan Defective  | Replace    |
| Radiator Defective                                     | Repair     |
| Switch Electrical Window Winder front left Malfunction | Replace    |
| Tail Light Left Scratched                              | Repair     |
| Front Bumper Damaged                                   | Repair     |
| Bonnet Residual Traces of Repair                       | Repair     |
| B • Pillar Left Residual Traces of Repair              | Repair     |
| Front Fender Left Paintwork • Scratched                | Repair     |
| Front Fender Right Residual Traces of Repair           | Repair     |
| Rear Fender Left Residual Traces of Repair             | Repair     |
| Rear Fender Right Dented                               | Repair     |
| Front Fender Right / Inner Tray Paintwork • Scratched  | Repair     |
| Door Front Left Paintwork • Scratched                  | Repair     |
| Door Front Right Paintwork • Scratched                 | Repair     |
| Door Rear Left Residual Traces of Repair               | Repair     |
| Door Rear Right Paintwork • Scratched                  | Repair     |
| Boot Lid / Hatch door Residual Traces of Repair        | Repair     |
| Rear bumper Damaged                                    | Repair     |
| Rocker Panel Right Dented                              | Repair     |
| Roof Paintwork • Scratched                             | Repair     |
| Windscreen Cracked                                     | Replace    |
| Steering Rack Boot Right Defective                     | Replace    |
| Tyre Rear Right Worn                                   | Replace    |
| Rim Front Left Scratched                               | Repair     |
| Rim Front Right Scratched                              | Repair     |
| Rim Rear Left Scratched                                | Repair     |
| Rim Rear Right Scratched                               | Repair     |
| Bolt(s) / Nut(s) Front Wheel Left Missing              | Replace    |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WAUZZZ8V1KA024481

1 / 15



## CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

| Damage  | Repair Way                                       |
|---|--|
| Bolt(s) / Nut(s) Front Wheel Right Missing            | Replace  |
| Bolt(s) / Nut(s) Rear Wheel Left Missing              | Replace  |
| Bolt(s) / Nut(s) Rear Wheel Right Missing             | Replace  |
| Sub Frame Scratched                                   | Repair   |
| Silencer Defective                                    | Repair   |
| Belly plates Damaged                                  | Replace  |
| Fuel Tank Sweat                                       | Repair   |
| CV Joint(s) Front Left (inner/outer) Welded           | Replace  |
| CV Joint(s) Boot(s) Front Right (inner/outer) Damaged | Replace  |
| Radiator Cradle Residual Traces of Repair             | Replace  |
| Engine  | Engine bay dirty                                 |
| Warning lights intermittent                           | Repair   |
| Body and Exterior                                     | Vehicle license disk missing                     |
| Undercarriage   | Vehicle undercarriage dirty                      |
| Interior  | Vehicle interior dirty and some panels scratched |
| Body and Exterior                                     | Dents and scratches on some body panels          |
| Body and Exterior                                     | Stone chips and spray work on some body panels   |
| Body and Exterior                                     | Residual traces of repair on some body panels    |
| Engine  | Radiator and Aircon condenser misaligned         |
| Engine  | Fan Cowley misaligned                            |
| Body and Exterior                                     | Some body panels misaligned                      |

### Brakes

#### Brake Test Results

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                                  |
| Front               | 2.91               | 3.67               | -                |                                  |
| Rear                | 2.29               | 2.3                | -                |                                  |
| Emergency / Parking | 1.87               | 2.02               | -                |                                  |

### Tyres and Rims

#### Tyre Specification & Measurement

|             | Size        | Load/Speed Index | Manufacture | Model      | Type* | Production Date | Tread Depth (mm) |
|-------------|-------------|------------------|-------------|------------|-------|-----------------|------------------|
| Front Left  | 225/45 R17  | 91W              | Continental | Contisport | V     | 4421            | 4 mm             |
| Front Right | 225/45Z R17 | 94W              | Kapsen      | Headking   | V     | 2122            | 3 mm             |
| Rear Left   | 225/45 R17  | 91W              | Continental | Contisport | V     | 0121            | 3 mm             |
| Rear Right  | 225/45 R17  | 91Y              | Michelin    | Primacy 3  | V     | 3618            | 0 mm             |
| Spare       | T125/70 R16 | 96M              | Hankook     | Temporary  | V     | 1518            | 3 mm             |

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                        | Code    | Description                               | Status |
|----|-------------------------------|---------|---|--------|
| 1  | 01-ENGINE CONTROL MODULE<br>1 | P308800 | STARTER RELAY ELECTRICAL FAULT IN CIRCUIT |        |

### Inspection Conditions

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

VIN: WAUZZZ8811A020753  
Report No: 201636093  
2 / 15  
DATE  
30/04/2024

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



### CONDITION REPORT

Report No: 2016360753


VIN: WAUZZZ8V1KA024481

DATE


30/04/2024

| Item                             | Value | Unit | Limit | Result |
|----------------------------------|-------|------|-------|--------|
| <b>Check shock absorber test</b> |       |      |       |        |
| Front left                       | 0.08  | mm   | 0.10  | PASS   |
| Front right                      | 0.09  | mm   | 0.10  | PASS   |
| Front weight                     | 1247  | kg   |       |        |
| <b>Brake test</b>                |       |      |       |        |
| Front left                       | 2.61  | mm   | 2.50  | 21 %   |
| Front right                      | 2.27  | mm   | 2.50  | 9 %    |
| Brake wear                       | 2.28  | mm   | 3.38  | 33 %   |
| Brake pad                        | 81    | %    |       |        |
| Brake disc                       | 32    | %    |       |        |
| Total weight                     | 1247  | kg   |       |        |


Brake and shock absorber report



Diagnostic report page 1




Diagnostic report page 2



Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016360753**

**DATE**  
VIN: WAUZZZ8V6K002024  
30/04/2024  
4 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

VIN: WAUZZZ8V1KA024481

5 / 15



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016360753**

**DATE**  
**30/04/2024**

VIN: WAUZZZ8V1KA024481

6 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

VIN: WAUZZZ8V1KA024481  
7 / 15



90 DEGREE REAR



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za





**CONDITION REPORT**

**Report No: 2016360753**

**DATE**  
**30/04/2024**

VIN: WAUZZZ8V1KA024481

8 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Spare wheel and Accessories



LICENSE DISC

VIN: WAUZZZ8V1KA024481  
9 / 15



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

VIN: WAUZZZ8V1KA024481

10 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Oil cap and dipstick



Water level

N: WAUZZZ8V1KA024481  
11 / 15



Engine



Windscreen



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

VIN: WAUZZZ8V1KA024481

12 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Front Fender Right



Bonnet

1KA024481  
13 / 15



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

VIN: WAUZZZ8V1KA024481

14 / 15

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Door Rear Left



Rear Fender Left

VIN: WAUZZZ8V1KA024481


15 / 15



B • Pillar Left



Rear bumper



Rear bumper



Tail Light Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za





CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Boot Lid / Hatch door




Roof




Rear Fender Right



Rocker Panel Right



Rim Front Right



Bolt(s) / Nut(s) Front Wheel Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Bolt(s) / Nut(s) Rear Wheel Right



Rim Rear Right



Bolt(s) / Nut(s) Rear Wheel Left



Rim Rear Left



Rim Front Left



Bolt(s) / Nut(s) Front Wheel Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016360753

DATE  
30/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



CV Joint(s) Boot(s) Front Right (inner/outer)



Belly plates



Belly plates



Engine



Fan



Radiator Cradle

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016360753

DATE  
30/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Sub Frame



CV Joint(s) Front Left (inner/outer)



Tyre Rear Right



Silencer



Fuel Tank



Steering Rack Boot Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za





**CONDITION REPORT**

Report No: 2016360753

DATE  
30/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016360753

DATE  
30/04/2024



Front Fender Right / Inner Tray



Belly plates



Radiator



Switch Electrical Window Winder front left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016360753**

**DATE**  
**30/04/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za