

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	21/12/2023		M57 Pretoria Road - 1619
Inspection Date	21/12/2023		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	BMW	Registration Number	HD63LBGP
Model	320I	Register Number	
VIN	WBA8A16080NU77305	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	120,742 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

	Damage	Repair Way
	Engine Oil Leak	Repair
	Engine Wiring Defective	Repair
	Hoses Broken	Replace
	Radiator Defective	Replace
	Air cleaner Broken	Repair
	Central Air Vent Defective	Repair
	Windscreen Washer Defective	Repair
	Air Conditioner Insufficient	Replace
	Tail Light Left Cracked	Replace
	Headlight Left Damaged	Replace
	Headlight Right Damaged	Replace
	Seat Rear Defective	Repair
	Door Panel Rear Left Defective	Repair
	Door Sealing Rubber Front Right Torn / Cut	Repair
	Dash Padding Damaged	Repair
	Side Mirror Right Paintwork • Scratched	Repair
	Front Bumper Damaged	Repair
	Bonnet Residual Traces of Repair	Repair
	Bonnet slam plate (Shock tower/ Inner tray) Residual Traces of Repair	Replace
	Front Fender Left Residual Traces of Repair	Replace
	Front Fender Right Residual Traces of Repair	Repair
	Rear Fender Right Paintwork • Scratched	Repair
	Front Fender Right / Inner Tray Damaged	Repair
	Door Front Left Paintwork • Scratched	Repair
	Door Front Right Residual Traces of Repair	Repair
	Door Rear Left Paintwork • Scratched	Repair
	Door Rear Right Paintwork • Scratched	Repair
	Boot Lid / Hatch door Paintwork • Scratched	Repair

Damage	Repair Way
Rear bumper Residual Traces of Repair	Repair
Rocker Panel Left Residual Traces of Repair	Repair
Rocker Panel Right Residual Traces of Repair	Repair
Roof Damaged	Repair
Wheel Cylinder / Caliper 2. Axle right Sweat	Repair
Shock Absorber Front Left Leak	Replace
Stabilizer Mounting Front Right Defective	Replace
Rear Axle Defective	Repair
Control Arm(s) Front Axle Left Defective	Replace
Control Arm(s) Front Axle Right Damaged	Replace
Control Arm(s) Front Rear Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Defective	Replace
Rim Front Left Dented	Repair
Rim Front Right Dented	Repair
Rim Rear Right Dented	Repair
Chassis Dented	Repair
Sub Frame Dented	Repair
Engine to silencer pipe Defective	Repair
Silencer Defective	Repair
Belly plates Damaged	Repair
Radiator Cradle Damaged	Replace
Jack Missing	Replace
Wheel Spanner Missing	Replace
Warning lights illuminated on dashboard	Repair
Signs of vehicle airbags deployed.	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.3	1.4	-	
Rear	2.76	3.05	-	
Emergency / Parking	2.52	2.77	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40 R18	88Y	Bridgestone	Potenza	V	2519	4 mm
Front Right	225/45 R18	91Y	Goodyear	Efficient	V	3521	4 mm
Rear Left	255/40 R18	95Y	Continental	ContiSport	V	2217	0 mm
Rear Right	245/35 R18	88Y	Goodyear	Eagle	V	4920	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DME(ENGINE-DIGITAL MOTOR ELECTRONICS)	10B105	INFORMATION OUTSIDE TEMPERATURE SENSOR,SIGNAL: FAU	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. SHOCK ABSORBER TEST COULD NOT BE PERFORMED.

Engine Compartment: Engine bay dirty. Brake fluid level ok. Oil level checked electronically. Left and right bonnet latches faulty. Radiator and Aircon condenser dented. Engine splash plate missing. Engine cover damaged. Computer box cover cracked.

Electrical Components and Instruments: Rain sensor cover missing. Park assistance faulty. Front left and right seat belt switches faulty. Hooter not working.

Lights: Vehicle has no lights working on front left and right headlights. Front right headlight bracket damaged.

Interior: Vehicle interior dirty and some interior panels scratched. Rear left and right seat belt behind seat. Rear middle seat belt behind seat.

Body • Exterior: Dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned. Stone chips on some body panels.

Poor residual traces of repair on some body panels. Bonnet struggles to open. Signs of impact damage to front and rear of vehicle.

Brakes: Oil sweat on rear right stub axle.

Axle and Suspension: Abnormal noise coming from front and rear suspension.

Tyres and Rims: Alloy rims scratched. Vehicle has no spare wheel. Front and rear tyre sizes different.

Undercarriage: Vehicle undercarriage dirty. Signs of tempering done to catalytic converter. Fuel tank scratched. Exhaust heat shields dented. Gearbox belly plate missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Automatic Transmission



Spare wheel Accessories




Oil cap









Front chassis



Rear chassis



Brake report



VIN: WBA8A16080NU77305

6 / 22

VIN: WBA8A16080NU77305

7 / 22



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

VIN: WBA8A16080NU77305

8 / 22



90 DEGREE RIGHT



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

VIN: WBA8A16080NU77305

10 / 22



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front Fender Left



Front Bumper

VIN: WBA8A16080NU77305

12 / 22



Front Bumper



Bonnet

VIN: WBA8A10801U77305
13 / 22



Front Fender Right



Door Front Right



Oil level



Air Conditioner

VIN: WBA8A16080NU77305

14 / 22



Dash Padding



Door Sealing Rubber Front Right



Door Rear Right



Rear Fender Right



Seat Rear



Rear bumper

VIN: WBA8A16080NU77305

16 / 22



Rear bumper



Tail Light Left

VIN: WBA8A1602 U77305
17 / 22

Boot Lid / Hatch door



Door Rear Left



Seat Rear



Door Panel Rear Left

VIN: WBA8A16080NU77305

18 / 22



Door Front Left



Side Mirror Right

VIN: WBA8A16080NU77305

19 / 22



Roof



Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Right / Inner Tray



Engine Wiring

VIN: WBA8A16080NU77305
20 / 22



Air cleaner



Windscreen Washer



Headlight Right



Headlight Left

VIN: WBA8A16080NU77305

21 / 22



Rocker Panel Right



Tyre Rear Left

VIN: WBA8A16080NU77305

22 / 22



Rocker Panel Left




Shock Absorber Front Left



Tyre Front Left



Radiator



Rim Front Left



Tyre Front Right



Rim Front Right



Engine to silencer pipe



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Control Arm(s) Front Axle Right



Control Arm(s) Front Axle Left



Engine Wiring



Front Bumper




Engine Wiring



Radiator Cradle



Radiator Cradle



Engine Wiring



Front Fender Right / Inner Tray




Engine



Sub Frame



Chassis



Belly plates



Engine to silencer pipe




Wheel Cylinder / Caliper 2. Axle right



Belly plates



Silencer



Control Arm(s) Front Rear Left



Tyre Rear Left



Rim Rear Right



Engine to silencer pipe



Rear bumper



Rear bumper



Rear bumper



Belly plates



Rear Axle



Engine Wiring



Hoses



Stabilizer Mounting Front Right



Water level



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Central Air Vent



CONDITION REPORT

Report No: 2016208595

DATE
21/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za