



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	31/01/2024		M57 Pretoria Road - 1619
Inspection Date	31/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	KP86BBGP
Model	FIESTA	Register Number	
VIN	WF0JXXGAHJKJ67161	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/05/2024
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	88,864 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Radiator Water Leak	Replace
Air cleaner Defective	Repair
Under bonnet insulation cover Defective	Repair
Switch Electrical Window Winder front left Broken	Replace
Windscreen Wiper Defective	Replace
Air Conditioner Insufficient	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Hood Lining Defective	Repair
Boot Carpet Damaged	Repair
Steering Wheel Trim Defective	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Left Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Dented	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Doorstopper Front Right Defective	Replace
Boot Lid / Hatch door Paintwork • Scratched	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WF0JXXGAHJKJ67161



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Damage	Repair Way
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Right Dented	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Dented	Repair
Windscreen Chipped	Repair
Wheel bearing Front Left Loose / Excessive Play	Replace
Tyre Front Right Damaged	Replace
Rim Front Left Dented	Repair
Rim Rear Left Dented	Repair
Cross Member Front Left Dented	Repair
Cross Member Front Right Damaged	Repair
Sub Frame Damaged	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Defective	Replace
Engine Noise Excessive	Repair
Engine management light illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.19	2.48	-	
Rear	1.59	1.46	-	
Emergency / Parking	1.22	1.54	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55 R16	91V	Hilo	Genesys	V	0222	3 mm
Front Right	205/55 R16	91V	Hilo	Genesys	V	0222	3 mm
Rear Left	205/55 R16	91V	Hilo	Genesys	V	0222	4 mm
Rear Right	205/55 R16	91V	Symmetry	SY300	V	0423	5 mm
Spare	175/65 R14	86T	Continental	Contipremuim	V	3519	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	P0111:00-64	IAT(INTAKE AIR TEMPERATURE) SENSOR 1 CIRCUIT RANGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Engine bay dirty.Brake fluid level ok.Bonnet slam plate cover damaged.Oil sump scra

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

VIN: W50MYG2M1K19167
Report No: 2016249247

2 / 18
DATE
31/01/2024

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016249247


VIN: WFOJXXGAHJKJ67161

DATE
31/01/2024

Brake and shock absorber report



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

VIN: WF0JXXG5116172024
DATE: 31/01/2024
4 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161

5 / 18



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
6 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

LF TYRE TREAD



LR TYRE TREAD

VIN: WF0JXXGAHJKJ67161
7 / 18

RR TYRE TREAD



RF TYRE TREAD



Spare wheel



Spare wheel Accessories



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
8 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024



LICENSE DISC



VIN PLATE OR STICKER

VIN: WF0JXXGAHJKJ67161
9 / 18



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
10 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024



Manual Transmission



Air Conditioner



Steering Wheel Trim



Hood Lining



Doorstopper Front Right



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
12 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Sill Panel Right



Door Front Right

VIN: WF0JXXGAHJKJ67161

13 / 18



Door Rear Right



Rear Fender Right



Seat Rear



Rear bumper



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
14 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Rear bumper



Boot Lid / Hatch door

VIN: WF0JXXGAHJKJ67161
15 / 18

Rear Fender Left



Door Rear Left



Door Front Left



Seat Rear



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
16 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

C • Pillar Left



Switch Electrical Window Winder front left

VIN: WFOJXXGAHJKJ67161

17 / 18



Seat Front Left



Side Mirror Left



Windscreen



Windscreen Wiper



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

VIN: WF0JXXGAHJKJ67161
18 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Front Fender Left



Front Bumper



Front Bumper



Bonnet



Front Fender Right



Air cleaner



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Headlight Left



Headlight Right



Tyre Front Right



Rocker Panel Right



Rocker Panel Left



Wheel bearing Front Left



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Rim Front Left



Cross Member Front Right



Cross Member Front Left



Gearbox



Engine



Radiator



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Belly plates



Sub Frame



Belly plates



Belly plates



Engine to silencer pipe



Inner Boot Floor Pan and Spare Wheel Well



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

Rim Rear Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Water level



Radiator Cradle



Radiator Cradle



Under bonnet insulation cover



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT**

Report No: 2016249247

DATE
31/01/2024

Boot Carpet



Inner Boot Floor Pan and Spare Wheel Well



CONDITION REPORT

Report No: 2016249247

DATE
31/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za