



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/01/2024		M57 Pretoria Road - 1619
Inspection Date	16/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	KT27WXGP
Model	AMAROK	Register Number	
VIN	WV1ZZZ2HZDH011794	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	16/01/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	271,691 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Wiring Damaged	Repair
Hoses Defective	Repair
Central Air Vent Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Heater operation Insufficient	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Sun Visor Right Damaged	Repair
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Replace



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axe Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	-
Rear	-	-	-	-
Emergency / Parking	-	-	-	-

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/70R16	112H	General	Radial	V	1722	3 mm
Front Right	265/70R16	112H	General	Radial	V	1722	4 mm
Rear Left	265/70R16	112H	General	Radial	V	1622	3 mm
Rear Right	265/70R16	112H	General	Radial	V	1822	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ENGINE MANAGEMENT LIGHTS ILLUMINATED ON CLUSTER.Electrical Components and Instruments: Heater is disconnected.

Lights: Interior panic handles damaged.

Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE
 ACCORDING TO THE AGE AND
 MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND
 MECHANICAL PARTS.

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT


VIN: WA617721Z1010376

Report No: 2016230376


2 / 12

DATE

16/01/2024



Shock test




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER

**CONDITION REPORT****Report No: 2016230376**

VIN: WV1ZZZ2HZDH011794

DATE

16/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016230376

DATE

VIN: WV1ZZZ2H760912024

4 / 12



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

VIN: WV1ZZZ2HZDH011794

5 / 12

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

VIN: WV1ZZZ2HZDH011794

6 / 12



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

VIN: WV1ZZZ2HZDH011794

7 / 12



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 10



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

VIN: WV1ZZZ2HZDH011794

9 / 12



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

ADDITIONAL 11



Water level



Heater operation



Engine Wiring



Hoses



Hoses



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

VIN: WV1ZZZ2HZDH011794

11 / 12



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

Door Rear Left



Tailgate



Rear bumper



Rear bumper



Rear Fender Right



Front Fender Right



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

Door Front Right



Door Rear Right



Side Mirror Right



Side Mirror Left



Roof



Seat Front Right





CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

Seat Front Left



Center Console / Cubbyhole + Lid



Central Air Vent



Central Air Vent



Sun Visor Right



CONDITION REPORT

Report No: 2016230376

DATE
16/01/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za