



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/01/2024		M57 Pretoria Road - 1619
Inspection Date	05/01/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KBH184MP
Model	POLO GTI	Register Number	
VIN	WVWZZZ6RZDY087210	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/10/2023
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	146,855 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Under bonnet insulation cover Damaged	Replace
Center Console / Cubbyhole + Lid Broken	Repair
Tail Light Left Cracked	Replace
Headlight Left Cracked	Replace
Headlight Right Damaged	Replace
Seat Front Right Torn / Cut	Repair
Door Handle Rear Right Defective	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Damaged	Repair
Roof Dented	Repair

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WVWZZZ6RZDY087210

1 / 18



**CONDITION REPORT**

Report No: 2016218352

DATE  
05/01/2024

Damage	Repair Way
Windscreen Cracked	Replace
Stabilizer Mounting Front Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Rear Right Worn	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Rim Front Right Dented	Repair
Rim Rear Right Dented	Repair
Rim Spare Wheel Cracked	Repair
Main Beam Right Dented	Repair
Engine to silencer pipe Defective	Replace
Catalytic converter Missing	Replace
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Front Left (inner/outer) Defective	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Warning lights illuminated on dashboard	Repair

**Brakes**

**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	3.32	3.7	-	
Rear	1.75	1.93	-	
Emergency / Parking	1.31	1.34	-	

**Tyres and Rims**

**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/40Z R17	87W	Farroad	FR26	V	0521	0 mm
Front Right	215/40 R17	87W	Hifly	HF805	V	2221	2 mm
Rear Left	175/65 R14	82T	Goodyear	GT2	V	4010	4 mm
Rear Right	205/40 R17	84W	Velocity	Speedmax	V	3016	0 mm
Spare	215/40Z R17	87W	Farroad	FRD26	V	0521	0 mm

\* Tyre Legend: V=Virgin, R=Recap

**Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P195000	COOLANT FAN FOR COOLANT DIFFICULTY OF MOVEMENT/BLO	

**Inspection Conditions**

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

**Comments**

General Comments: VEHICLE LICENSE DISK INSIDE CUBBYHOLE.SHOCK ABSORBER TEST COULD NOT BE PERFORMED.  
 Engine Compartment: Engine bay dirty. Brake fluid level ok. Engine cover missing. Aftermarket performance air filter fitted to vehicle. Oil cooler strapped with cable ties. Engine fan blades scratched. Signs of rodent in engine bay.  
 Electrical Components and Instruments: Driver window switches mechanism damaged.  
 Lights: Front left fog light not working.  
 Interior: Vehicle interior dirty and some interior panels scratched. Loose sound wiring inside boot of vehicle.  
 Body • Exterior: Dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned. Stone chips on some body panels.

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za

**CONDITION REPORT**

VIN: RA4AWZ7692016218352

Report No: 2016218352

2 / 18

DATE

05/01/2024

Residual traces of repair on some body panels. Front left and right inner fender liners damaged. Signs of impact damage to front of vehicle. Rear number plate missing.

Axle and Suspension: Abnormal noise coming from front and rear suspension.

Tyres and Rims: Alloy rims scratched. Rear left and right tyre sizes different.

Undercarriage: Vehicle undercarriage dirty. Engine splash plate missing. Non standard exhaust fitted to vehicle. Bolt missing on front left inner CV joint.

**Concluding Remarks**

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

**Technician**

Sibusiso Mokase


This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT


Report No: 2016218352  
VIN: WVWZZZ6RZDY087210  
DATE: 05/01/2024




Brake test report




Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3



Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

VIN: WVVZZZ6R5D0097204  
DATE: 05/03/2024  
4 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

VIN: WVVZZZ6RZDY087210

5 / 18



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016218352**

**DATE**  
**05/01/2024**

VIN: WVVZZZ6RZDY087210

6 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

VIN: WVVZZZ6RZDY087210

7 / 18



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016218352**

**DATE**  
**05/01/2024**

VIN: WVVZZZ6RZDY087210

8 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Spare wheel Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016218352**

**DATE**  
**05/01/2024**

VIN: WVVZZZ6RZDY087210  
10 / 18


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024




Oil cap and dipstick



Automatic Transmission


087210  
11 / 18



Center Console / Cubbyhole + Lid



Door Sealing Rubber Front Right



Seat Front Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

VIN: WVVZZZ6RZDY087210

12 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Door Front Right



Side Mirror Right

VIA WWW.ZZZZ687... 087210  
13 / 18



Front Fender Right



Door Rear Right



Rear Fender Right



Door Handle Rear Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

VIN: WVVZZZ6RZDY087210

14 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Rear bumper



Rear bumper



Tail Light Left



Rear Fender Left



Door Rear Left



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

VIN: WWWZZZ6RZDY087210

16 / 18

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Door Front Left



Windscreen




Front Bumper



Front Bumper



Bonnet



Engine

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016218352**

**DATE**  
**05/01/2024**

VIN: WVVZZZ6RZDY087210

18 / 18


DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Engine Wiring



Side Mirror Left



Roof



Headlight Left



Front Fender Left



Parcel Tray

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016218352

DATE  
05/01/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024




Spare Tyre



Rim Spare Wheel



Main Beam Right



Headlight Right



Control Arm Bush(es) Front Axle Right



Rocker Panel Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Rim Rear Right



Control Arm Bush(es) Front Axle Left



Rim Front Right



Rim Front Left



Tyre Front Left



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016218352

DATE  
05/01/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Gearbox



Engine to silencer pipe



Engine Wiring



Stabilizer Mounting Front Left



Radiator Cradle



Belly plates

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

Report No: 2016218352

DATE  
05/01/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Tyre Rear Right



Rocker Panel Right



Rocker Panel Left



Engine to silencer pipe



CV Joint(s) Front Left (inner/outer)



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016218352

DATE  
05/01/2024



Catalytic converter



Water level



Under bonnet insulation cover

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



**CONDITION REPORT**

**Report No: 2016218352**

**DATE**  
**05/01/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za