



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	01/07/2025		M57 Pretoria Road - 1619
Inspection Date	01/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LGG289MP
Model	POLO GP 1.8 TSI GTI 141KW 5-DR DSG [2016-2018]	Register Number	
VIN	WVWZZZ6RZHY071232	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2026
Color	RED	Power / Displacement	
Year Model	2016	Paint Finish	C - COMMON
Km Reading	203,062 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025



Damage	Repair Way
Engine Oil Leak	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair

Brakes

Brake Test Results

	Left	Right	Axe Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	3.1	2.8	-	
Rear	1.7	1.3	-	
Emergency / Parking	0.8	0.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/40R17	87V	Continental	Contact	V	1418	3 mm
Front Right	215/40R17	87V	Continental	Contact	V	1418	3 mm
Rear Left	215/40R17	87V	Continental	Contact	V	1418	2 mm
Rear Right	215/40R17	87W	Hilo	Vantage xu1	V	1621	3 mm
Spare	T125/60R18	94M	Continental	Temporary	V	2518	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE/SPORADIC	U101100	SUPPLY VOLTAGE VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025

Vehicle Details		Owner Details	
Name/Cat.	Cat.	License plate:	Cat.
Model:	2016	Mileage:	200000
Reg. date:	2025/05/01	Manufacture:	VW POLO GTE
Engin no:		Model:	GTE
Transm:		VIN:	WAUW220420W1123
Test time:	05/07		

Test results:

Category	Result
Brake test	Pass
Front axle - 10% incl.	Pass
Front axle - 7% incl.	Pass
Shock absorber test	Pass
Front axle	OK
Front axle	OK
Front axle	OK
Total weight	1245 kg

Brake test:

Parameter	Value	Unit	Requirement	Result
Front axle	1.14	km/h	> 0.75	Pass
Front axle	1.22	km/h	> 0.75	Pass
Front axle	1.27	km/h	> 0.75	Pass
Total weight	1.20	km/h	> 0.75	Pass

Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT




Report No:
2016931041
DATE
01/07/2025



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232




CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025



Expection bottle



Parking Brake Performance



Water level



Bonnet



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT



Report No:
2016931041
DATE
01/07/2025



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZHY071232



CONDITION REPORT




Report No:
2016931041
DATE
01/07/2025




Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Boot Lid / Hatch door



Engine



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ6RZH071232