Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20250909094140
Test Time: 2025-09-09 09:41:40
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZLU067392

Odometer Reading: 119502km
License Plate: KB32YNGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	2
03 - Brakes 1	3
08 - Air Conditioning	0
09 - Electronic central electric	2
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	3
44 - Power Steering	0
5F - Information electronics 1	4

DTC (16)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P06E900	Engine Starter Performance	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B13BCF2	Multiple collision brake No function	Passive/Sporadic
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B121715	Left low beam headlamp bulb Circuit open or short to positive	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U140600	Static current too high	Passive/Sporadic

5F - Information electronics 1 (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
U111100	Function restriction caused by missing message	Passive/Sporadic
U11B800	Interface for external media No communication	Passive/Sporadic

Technician Notes

2017006555

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.