Shop: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20240326114333
Test Time: 2024-03-26 11:43:33
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: AAVZZZAWZNU029474
Odometer Reading: 62820km
License Plate: KK84HDGP

Customer Information

Name: MFC Dekra Nedbank Auction House
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	2
03 - Brakes 1	0
08 - Air Conditioning	0
09 - Electronic central electric	8
15 - Airbag	1
17 - Instrument cluster	2
19 - Gateway	2
44 - Power Steering	2
5F - Information electronics 1	2

DTC (19)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Active/static
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static

09 - Electronic central electric (8 DTCs)

DTC	Description	Status
B11E915	Left rear turn signal bulb Open circuit/short circuit to B+	Active/static
B12D015	Left turn signal light bulb Open circuit/short circuit to B+	Active/static

B12C215	Left tail lamp Circuit open or short to positive	Active/static
B12C315	Right brake light bulb Open circuit/short circuit to B+	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
B131FF4	Driver side rear window regulator Voltage supply above upper limit	Passive/Sporadic
U121100	Driver side rear window regulator motor No communication	Passive/Sporadic
B1320F4	Passenger side rear window regulator Voltage supply above upper limit	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B12F114	Front passenger airbag indicator Circuit open or short to ground	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U111000	Function restriction caused by communication interruption	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power Steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
U111100	Function restriction caused by missing message	Passive/Sporadic

Technician Notes

2016318721

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.