Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSX22P507112006

Odometer Reading: 244872km
License Plate: LH82KWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device information

Scanner: MaxiSys MS906 BT
Version: V11.70

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	8
ABS/VSC/TRC	2
SRS airbag	2
Combination meter	1
Immobilizer	0

DTC (13)

Engine and ECT (8 DTCs)

DTC	Description	Status
P0102	Mass air flow (MAF) circuit low	Pending
P0113	Intake air temperature circuit input high	Current
P0135	Oxygen sensor heater circuit (bank 1 sensor 1)	Pending
P0102	Mass air flow (MAF) circuit low	Current
P0135	Oxygen sensor heater circuit (bank 1 sensor 1)	Current
P0102	Mass air flow (MAF) circuit low	History
P0113	Intake air temperature circuit input high	History
P0135	Oxygen sensor heater circuit (bank 1 sensor 1)	History

ABS/VSC/TRC (2 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	Current
C1201	Engine/EV control system malfunction	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History

B1806	P squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Technician Notes

2017257542

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.