Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261116150712
Test Time: 2026-11-16 15:07:12
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Fortuner/--
VIN: AHTZZ69G805042969

Odometer Reading: 332657
License Plate: HSL209MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.90

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System		Status/DTC
Engine		1
Electronically controlled transmission (ECT)		0
SRS airbag		4
Cruise control	ADAS	0
Immobilizer		0
Headlamp auto leveling	ADAS	0

DTC (5)

Engine (1 DTC)

DTC	Description	Status
P1604	Startability fault	History

SRS airbag (4 DTCs)

DTC	Description	Status
B1821	Side squib (drive side) circuit open	Current
B1801	Driving side squib circuit open	History
B1821	Side squib (drive side) circuit open	History
B1826	Side squib (passenger side) circuit open	History

Technician Notes

2017325955

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.