Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261109143829
Test Time: 2026-11-09 14:38:29
Technician: Werner

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Kuv100/--
VIN: MA1VC2RBCL6085891

Odometer Reading: 80741
License Plate: KGJ978MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V3.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
Engine management system	9
Anti-Lock braking system	2
Supplementary restraint system	3
Instrument cluster	10
Electronic power steering	0
Mahindra body function module	6
Reverse park assist system	4
Immobiliser	8

DTC (42)

Engine management system (9 DTCs)

DTC	Description	Status
P056217	Signal range check for battery sensor signal below minimum limit	Other
P056216	Signal range check for ignition key input below minimum limit	Other
P33A000	Primary EMS-ICU1 authentication: Immobilized condition/Immobilizer authentication failed	Other
P33A600	Primary EMS-ICU1 authentication: signature1 using page_1 failed	Other
P33AB00	Primary EMS-ICU1 authentication: signature 1 mismatch	Other
P164100	EMS Software reset error	Other
P33AD00	Primary EMS-ICU1 authentication: IMMTRG timeout	Other
P33AE00	Primary EMS-ICU1 authentication: invalid trigger error	Other

U201600	ABS request torque increment signal content error	Other

Anti-Lock braking system (2 DTCs)

DTC	Description	Status
U110100	Node absent - EMS	Other
U300616	Under voltage error	Other

Supplementary restraint system (3 DTCs)

DTC	Description	Status
U110187	Lost comm with EMS	Other
B142A16	Battery voltage low	Other
U110587	Lost comm with IC	Other

Instrument cluster (10 DTCs)

DTC	Description	Status
B2F3E02	MIL TT failure	Other
B2F3F02	Enginer start stop failure	Other
U120500	IC bus off	Other
U110100	EMS node absent	Healed
U100100	EMS message time out. Applicable to (EMS1, EMS2 , EMS4, EMS8, EMS12).	Healed
U110300	ABS/ESC node absent	Healed
U100400	MBFM message time out. Applicable to (MBFM1 and MBFM7).	Healed
U110800	IS node absent	Current
U200400	EMS engine speed signal content error	Healed
B2F3816	IC undervoltage	Other

Mahindra body function module (6 DTCs)

DTC	Description	Status
B110016	Power(Battery) under voltage	Others
B110001	Battery 3(CDL + frnt wiper)Fault	Others
U110100	EMS node absent	Others
U110300	ABS/ESC node absent	Others
U110800	Infotainment node absent	Current
U130400	VIN mismatch in MBFM	Others

Reverse park assist system (4 DTCs)

DTC	Description	Status
B100116	RPAS ECU supply voltage lower limit exceeded	Healed

B100216	RPAS sensor supply lower limit exceeded	Healed
U100100	EMS message time out error	Healed
U110100	EMS node absent	Healed

Immobiliser (8 DTCs)

DTC	Description	Status
B2F4100	Tag auth failed	Other
B2F4500	Authentication failed/time out	Other
B2F4400	No ECM challenge	Other
B2F4900	Please refer to vehicle service manual !	Other
U110400	MBFM node absent	Other
U110500	IC node absent	Other
U100400	MBFM message time out error	Other
U121700	IMMO bus off error	Other

Technician Notes

2017323115

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.