Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250117130858
Test Time: 2025-01-17 13:08:58
Technician: Werner

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV/--
VIN: VF15RSV0A58174603

Odometer Reading: 124403
License Plate: JVP137MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V14.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
Injection	6
ABS	8
Airbag / pretensioners	4
Instrument panel	6
UCH	5
Variable PAS	2
Radio	5
Air conditioning	2
Hands-free module	4

DTC (42)

Injection (6 DTCs)

DTC	Description	Status
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF2	Computer Internal electronic fault	Memory
DTC061A61	Computer Internal electronic fault	Memory
DTC083362	Clutch switch signal consistency	Memory

DTC1525F3	Consistent multiplex signals for CC/SL The data supplied to the cruise control or speed limiter are not correct.	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS (8 DTCs)

DTC	Description	Status
DTC406C13	Vacuum sensor circuit Open circuit	Memory
DTC406C96	Vacuum sensor circuit Internal component failure	Memory
DTCC02800	Steering wheel angle multiplexed emission	Memory
DTCC12600	Steering wheel angle sensor multiplex signals	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCC42200	Invalid UCH multiplex signals	Memory
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

Airbag / pretensioners (4 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer.	Memory
DTC80D224	Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer.	Memory
DTCF00316	Computer supply voltage Feed voltage too low	Memory
DTCF00317	Computer supply voltage Feed voltage too high	Memory

Instrument panel (6 DTCs)

DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Active

DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH (5 DTCs)

DTC	Description	Status
DTC951924	Neutral switch	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC956023	Start of clutch switch travel circuit	Memory
DTC956024	Start of clutch switch travel circuit	Memory
DTC956123	End of clutch switch travel circuit	Memory

Variable PAS (2 DTCs)

DTC	Description	Status
DTCF00313	Computer power supply Open circuit	Memory
DTCF00317	Computer power supply Excess voltage	Memory

Radio (5 DTCs)

DTC	Description	Status
DTC931513	FM1 receiver Open circuit	Memory
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer configuration Internal electronic fault	Memory
DTC934749	Computer Internal electronic fault	Memory
DTC93CF73	Key jammed Internal electronic fault	Memory

Air conditioning (2 DTCs)

DTC	Description	Status

DTC910549	Computer Internal electronic fault	Memory
DTCF00316	Computer supply voltage Low voltage	Memory

Hands-free module (4 DTCs)

DTC	Description	Status
DTCA0334A	Dongle	Memory
DTCA05111	Steering lock Short circuit to earth.	Memory
DTCA0571C	Steering column lock protection Component failures	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes

2016724443

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.