Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20260422110551
Test Time: 2026-04-22 11:05:51
Technician: Werner

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3'/320i_B48/--
VIN: WBA5F32070FL70102
Odometer Reading: 211597
License Plate: KJ34LKGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V25.00
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (21)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	2
EGS (Electronic Transmission Management)	0
DSC (Dynamic Stability Control)	0
ACSM (Airbag-Advanced Crash Safety Module)	0
KOMBI (Instrument Cluster)	0
BDC (Body Domain Controller)	2
RVC (Rear View Camera) ADAS	0
ZGM (Central Gateway Module)	0
PMA (Parking Manoeuvring Assistant) ADAS	5
EPS (Electric Power Steering)	0
RAM (Receiver audio module)	0
VIP (Virtual integration system)	0
FLEL (Frontal Light Electronics Left) ADAS	0
FLER (Frontal Light Electronics Right) ADAS	0
FZD (Roof Function Center)	1
GWS (Gear Selector Switch)	0
TCB (Combox Emergency Call)	0
HUH (Headunit High)	10
CON (Controller)	0

IHKA (Integrated Automatic Heating And A/C System)	1
CAS (Car Access System)	2

DTC (21)

DME (Engine-Digital Motor Electronics) (2 DTCs)

DTC	Description	Status
150302	Ignition, cylinder 3: Combustion period too short	Intermittent
030E06	Power management: Reduction or shutdown of individual electrical consumer	Intermittent

PMA (Parking Manoeuvring Assistant) (5 DTCs)

DTC	Description	Status
803268	Ultrasonic sensor, front centre left: Blindness identified	Permanent
803269	Ultrasonic sensor, front centre right: Blindness identified	Intermittent
803270	Ultrasonic sensor, front outer right: Blindness identified	Intermittent
803272	Ultrasonic sensor for PMA, front right side: Blindness identified	Intermittent
D40518	PMA, K-CAN6: Communication fault	Intermittent

FZD (Roof Function Center) (1 DTC)

DTC	Description	Status
801A55	Anti-theft alarm system: Alarm signal - details in alarm memory	Intermittent

HUH (Headunit High) (10 DTCs)

DTC	Description	Status
031794	HU-H: Function restriction telephone calls	Intermittent
B7F89E	HU-H: Back end certificates not valid	Intermittent
031790	HU-H: Function restriction connection establishment / coupling Bluetooth	Intermittent
031793	HU-H: Function restriction connection WLAN	Intermittent
03179A	HU-H: Function restriction connection Apple CarPlay	Intermittent
031795	HU-H: Function restriction telephone book	Intermittent
031796	HU-H: Function restriction telephone list	Intermittent
031791	HU-H: Function resrtriction Bluetooth connection	Intermittent
03179D	HU-H: Function restriction SMS	Intermittent
031797	HU-H: Functional limitation for Bluetooth audio	Intermittent

IHKA (Integrated Automatic Heating And A/C System) (1 DTC)

DTC	Description	Status

E7147E	No message (information, data, target object, cruise control 2), receiver IHKA, transmitter FRS / SAS	Permanent

CAS (Car Access System) (2 DTCs)

DTC	Description	Status
8040F1	Crypto data in a key	Intermittent
804415	Radio remote control: Battery undervoltage	Permanent

Technician Notes

2017224744

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.