DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	05/11/2026		
Inspection Date	05/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	CK70FDGP
Model	POLO VIVO 1.4 BASE 5-DR [2010-2015]	Register Number	
VIN	AAVZZZ6SZCU019464	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2012	Paint Finish	TWO COAT UNI
Km Reading	372,681 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026





Damage	Repair Way
Engine Wiring Defective	Repair
Fan Damaged	Replace
Fan Belt Damaged	Replace
Radiator Damaged	Replace
Hooter Defective	Replace
Radio/CD/USB Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Replace
Tail Light Left Cracked	Replace
Tail Light Right Cracked	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Defective	Repair
Door Handle Front Left Damaged	Replace
Door Handle Front Right Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Lock Front Right Damaged	Replace
Dash Padding Damaged	Replace
Carpet Front Damaged	Repair
Gear Lever Dust Boot Damaged	Repair
Steering Wheel Trim Damaged	Replace
Side Mirror Right Cracked	Replace
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Replace
Door Front Left Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Damaged	Repair
Windscreen Cracked	Replace
Brake Pad 1. Axle left Excessive Wear & Tear	Replace
Parking Brake Performance Insufficient	Repair
Steering Rack Boot Left Damaged	Replace
Steering Rack Boot Right Defective	Replace
Shock Absorber Rear Right Leak	Replace
Stabilizer Mounting Front Left Damaged	Replace
Wheel bearing Front Left Loose / Excessive Play	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026

Damage	Repair Way
Tyre Rear Right Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Main Beam Left Damaged	Repair
Main Beam Right Damaged	Repair
Chassis Dented	Repair
Sub Frame Dented	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Steering Noisy	Repair
Brakes Insufficient	Repair
Engine Performance Insufficient	Repair
Engine Noise Excessive	Repair
Gear Selections Malfunction	Repair
Cluster cracked	Replace
Interior bonnet release handle missing	Replace
Wiper valance damaged	Replace
Warning lights illuminated on dashboard	Repair
Boot release handle damaged	Replace
Front left and right tyre sizes different	Repair
Engine oil sump damaged	Replace
Fan Cowley damaged	Replace
Rear right tyre regrooved	Replace
Rear bumper stiffener damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.38	2.67	-	
Rear	0.65	0.76	-	
Emergency / Parking	0	0	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Goodride	Radial	V	1623	0 mm
Front Right	165/70R14	81T	Goodyear	Assurance	V	2824	0 mm
Rear Left	175/65R14	86T	Encore	Reflex	V	3321	0 mm
Rear Right	185/70R14	88H	Windforce	Catchfors	V	0624	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	44-POWER STEERING	U140000	FUNCTION RESTRICTION,DUE TO LOW VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Engine Compartment: Traces of repair work done on the engine. Computer box strapped with cable ties. Some bolts are missing from the engine oil sump.
Electrical Components and Instruments: Hooter not working. Radio not working.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels. Body panels are misaligned. Stone chips and spray marks on body panels. Dents and scratches on body panels.Boot does not open. Signs of impact damage to the front of the vehicle.
Axle and Suspension: Excessive noise coming from front suspension.
Undercarriage: Loose bolts on gearbox.
Road Test: Vehicle unsafe to drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT


Report No:
2017321514
DATE
05/11/2026



Brake and shock absorber repor



Front chassis



Diagnostic report



Fan Cowley



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Wiper valance



Manual Transmission



Boot release handle



Engine oil sump



Rear bumper stiffener



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

CLIENT SIGNATURE



Front Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Rim Front Right



Rim Rear Right



Rear Fender Right



Rear Fender Right



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT


Report No:
2017321514
DATE
05/11/2026



Door Handle Front Right



Side Mirror Right



Door Sealing Rubber Front Right



Seat Front Right



Seat Front Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Seat Rear



Steering Wheel Trim



Dash Padding



Headlight Right



Headlight Left



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Windscreen



Front Fender Left



Rim Front Left



Bolt(s) / Nut(s) Front Wheel Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Rear Fender Left



Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Left



Door Handle Front Left



Seat Front Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Rear bumper



Rear bumper


Boot Lid / Hatch door


Tail Light Left


Tail Light Right


Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Bonnet slam plate (Shock tower/ Inner tray)



Water level




Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Right / Inner Tray



Engine Wiring



Fan Belt

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT


Report No:
2017321514
DATE
05/11/2026



Fan



Steering Rack Boot Left



Main Beam Left



Engine Wiring



Engine Wiring



Hooter

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Gear Lever Dust Boot



Radio/CD/USB



Front Fender Right / Inner Tray



Bolt(s) / Nut(s) Front Wheel Right



Control Arm Bush(es) Front Axle Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464


DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Shock Absorber Rear Right



Tyre Rear Left



Rear Fender Left / Inner Tray



Sill Panel Left



Brake Pad 1. Axle left



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026




Front Bumper


Front Bumper


Front Bumper


Engine to silencer pipe


Parking Brake Performance


Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Tyre Front Left



Steering Rack Boot Right



CV Joint(s) Boot(s) Front Right (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)



Engine Wiring



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Belly plates



Belly plates



Chassis



Chassis



Wheel bearing Front Left



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Sub Frame



Radiator



Radiator Cradle



Main Beam Right



Tyre Rear Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464

DEKRA

CONDITION REPORT

Report No:
2017321514
DATE
05/11/2026



Inner Boot Floor Pan and Spare Wheel Well



Engine to silencer pipe



Gearbox



Hood Lining



Carpet Front



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZCU019464