DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park - GT**
Requested Date	**13/08/2025**		
Inspection Date	**13/08/2025**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**VOLKSWAGEN**	Registration Number	**JYW135MP**
Model	**POLO VIVO GP 1.4 CONCEPTLINE 5-DR [2014-2016]**	Register Number	
		Date Of First Licensing	
VIN	**AAVZZZ6SZFU032849**	Last COR	
Engine Number		License Expiry Date	**30/04/2024**
Doors	**5**	Power / Displacement	
Color	**WHITE**	Paint Finish	**TWO COAT UNI**
Year Model	**2015**	Fuel	**PETROL**
Km Reading	**452,129 KM**	Transmission	**MANUAL**
Cab / Body Type	**HATCHBACK**		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No: 2016978074
DATE 13/08/2025



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Replace
Expansion Bottle Defective	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Headlight Right Defective	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Rear Fender Left Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Windscreen Damaged	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Repair
Tyre Rear Left Damaged	Replace
Tyre Rear Right Worn	Replace
Engine to silencer pipe Welded	Replace
Gearbox Oil Sweat	Repair
Radiator Cradle Damaged	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.61	2.66	-	
Rear	1.44	1.45	-	
Emergency / Parking	1.06	1.19	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Goodride	Radial	V	1613	0 mm
Front Right	175/65R14	82T	Dunlop	Sp	V	4122	0 mm
Rear Left	185/60R14	82H	Royal black	Radial	V	1822	2 mm
Rear Right	175/65R14	82H	Westlake	Radial	V	3521	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P0118:00/0-0280:000	ENGINE COOLANT TEMPERATURE SENSOR 1 CIRCUIT HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose. sump damaged.
Tyres and Rims: left rear tire has a flat spot.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849


DEKRA

CONDITION REPORT


Report No:
2016978074
DATE
13/08/2025



Brake test.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT


Report No:
2016978074
DATE
13/08/2025



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



VIN PLATE OR STICKER


ENGINE 1


Undercarriage front.


Undercarriage rear.


Oil cap and dipstick.


Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



Expansion Bottle



Headlight Right



Front Bumper



Front Bumper



Bonnet



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



Door Front Right



Door Rear Right



Windscreen



Tail Light Left



Windscreen Wiper



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025




Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Radiator Cradle



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849

DEKRA

CONDITION REPORT

Report No:
2016978074
DATE
13/08/2025



Gearbox



Engine



Engine Wiring



Engine Wiring



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU032849