DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	17/11/2026		
Inspection Date	17/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	JH31BTGP
Model	POLO 1.0 TSI 70KW TRENDLINE 5-DR [2019-2021]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZKU097989	Last COR	
Engine Number		License Expiry Date	28/02/2027
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2019	Fuel	PETROL
Km Reading	164,346 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026





Damage	Repair Way
Windscreen Wiper Damaged	Replace
Fog Light Front Left Scratched	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Seat Belt Rear Right Damaged	Replace
Hood Lining Dirty	Repair
Door Sealing Rubber Front Right Damaged	Replace
Boot Carpet Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Right Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Paintwork • Scratched	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Brake disc 1. Axle left Excessive Wear & Tear	Replace
Brake disc 1. Axle right Excessive Wear & Tear	Replace
Brake fluid level Insufficient	Replace
Tie Rod End left Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Damaged	Repair
Rim Front Right Scratched	Repair
Belly plates Damaged	Repair
Fuel Tank Damaged	Repair
Warning lights illuminated on dashboard	Repair
Driver's electrical window switch unit damaged	Replace
Front tyres size differs	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No: 2017326456
DATE 17/11/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.41	3.46	-	
Rear	2.58	2.04	-	
Emergency / Parking	1.85	2.03	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/45Z R17	88W	Tomket	Radial	V	4025	4 mm
Front Right	205/50 R17	89V	Goodyear	Efficient	V	1619	3 mm
Rear Left	215/45 R17	91W	Dunlop	Sp-Sport	V	4121	4 mm
Rear Right	215/45 R17	87W	Symmetry	SY201	V	2218	0 mm
Spare	185/70 R14	88H	Falken	Sincera	V	1919	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P305400	STARTER DOES NOT TURN, MECHANICALLY BLOCKED OR ELE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / STONE CHIPS AND SPRAY WORK ON BODY PANELS / SIGNS HAIL DAMAGE ON BODY PANELS / VEHICLE INTERIOR DIRTY AND PANELS SCRATCHED / BOTTOM OF ENGINE AND GEARBOX FULLY COVERED.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



ENGINE 1



ENGINE 2



Front chassis



Rear chassis



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT


Report No:
2017326456
DATE
17/11/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Diagnostic report page 2



Diagnostic report page 3




Driver electrical window switc



Steering Wheel Trim



Hood Lining



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Door Sealing Rubber Front Right



Seat Belt Rear Right



Seat Rear



Sill Panel Right



C • Pillar Right



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Seat Front Left



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Boot Carpet



Boot Carpet



Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Windscreen Wiper



Bonnet




Bonnet



Windscreen



Roof



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Door Front Right



Door Rear Right



Water level



Rim Front Right



Brake disc 1. Axle left



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Sill Panel Left



Rim Front Left



Control Arm Bush(es) Front Axle Left



Brake disc 1. Axle right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Fog Light Front Left



Front Bumper



Belly plates



Belly plates



Belly plates



Tie Rod End left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989

DEKRA

CONDITION REPORT

Report No:
2017326456
DATE
17/11/2026



Fuel Tank



Tyre Rear Right



Brake fluid level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZKU097989