DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	11/11/2026		
Inspection Date	11/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	LFG539NW
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2024-2026]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P707162937	Last COR	
Engine Number		License Expiry Date	31/01/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2025	Fuel	DIESEL
Km Reading	101,559 KM	Transmission	MANUAL
Cab / Body Type	OTHERS		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026





Damage	Repair Way
Caps Missing	Replace
Bonnet stay and shocks Missing	Replace
Radio/CD/USB Missing	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Left Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Welded	Repair
Front Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Sliding Door Residual Traces of Repair	Repair
Windscreen Chipped	Repair
Brake Drum 2. Axle left Defective	Repair
Brake Drum 2. Axle right Defective	Repair
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Spring Shackle Bush Rear Axle Right Missing	Replace
Tyre Front Right Smooth	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Gearbox Oil Leak	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Signs of poor repair work done on some body panels
Body exterior	Signs of spray work done on some body panels
Boot not closing properly	Repair
R/F tire deferred size	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	5.4	4.1	-	
Rear	0.4	1.2	-	
Emergency / Parking	0.3	1.6	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15	106/104S	Toyo	Ho7	V	0924	3 mm
Front Right	205/70R15	109/107R	Windforce	Touring max	V	0724	0 mm
Rear Left	195R15	106/104R	Double king	Dk 256	V	3424	2 mm
Rear Right	195R15	106/104R	Powertrac	Vanmarch	V	3525	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937


DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



ENGINE 2




CHASSIS



ENGINE 1



Diagnostic report



Shock and brake report



No spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Seat Rear



Seat Rear (2. Row)



Seat Front Left



Water level



Caps



Bonnet stay and shocks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Headlight Left




Bonnet




Windscreen



Radio/CD/USB



Parking Brake Performance



Service Brake Performance Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Front Bumper



Bonnet



Front Fender Left



Side Mirror Left



Door Front Left



Sliding Door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Tail Light Left



Tail Light Right


Rear Fender Right


Door Front Right


Spring Shackle Bush Rear Axle Right


Brake Drum 2. Axle left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Brake Drum 2. Axle right



Gearbox



Tyre Front Right



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937

DEKRA

CONDITION REPORT

Report No:
2017323675
DATE
11/11/2026



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P707162937