Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231220132151
Test Time: 2023-12-20 13:21:51
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU004769
Odometer Reading: 100939
License Plate: FSK615L

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.00
Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	2
09 - Electronic central electric	0
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	1
25 - Anti-Theft Immobilizer	1
44 - Power Steering	0
56 - Radio	0

DTC (6)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1603:00/05 635:000	Ctrl. module faulty -	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status

U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

Technician Notes

2016207725

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.