Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZJU061432

Odometer Reading: 536682km
License Plate: HGK330FS

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	19
03 - Brakes 1	5
08 - Air conditioning	1
09 - Electronic central electric	9
15 - Airbag	3
17 - Instrument cluster	3
19 - Gateway	2
44 - Power steering	1
5F - Information electronics 1	6

DTC (49)

01 - Engine Control Module 1 (19 DTCs)

DTC	Description	Status
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P029900	Turbocharger/supercharger underboost	Passive/Sporadic
P190D00	Coolant pump for charge pressure cooler ,Mechanical malfunction	Passive/Sporadic
P026A00	Charge Air Cooler Efficiency Below Threshold	Passive/Sporadic
P050700	Idle control system ,Speed higher than specified value	Passive/Sporadic
P000B00	'B' Camshaft Position Slow Response (Bank 1)	Passive/Sporadic
P055600	Brake booster pressure sensor circuit range/performance	Passive/Sporadic
P014C00	O2 Sensor Bank 1 Sensor 1 ,Slow Response - Rich to Lean	Passive/Sporadic
P000A00	A Camshaft Position (CMP) slow response (bank 1)	Passive/Sporadic

P001100	A Camshaft Position (Bank1) ,Timing over-advanced or System Performance	Passive/Sporadic
P034100	Camshaft Position Sensor ,Implausible signal	Passive/Sporadic
P001600	Crankshaft Position (CKP)-Camshaft Position (CMP) , Correlation (bank 1 sensor A)	Passive/Sporadic
P036600	Camshaft position sensor exhaust bank 1 ,Implausible signal	Passive/Sporadic
P008800	Fuel rail/system pressure - too high	Passive/Sporadic
P030000	Random Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030300	Cylinder 3 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P042000	Catalyst System Efficiency Below Threshold Bank 1 ,No Sub Type Information	Active/static

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Active/static
C10A416	Low pressure sensor power supply ,Voltage too low	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B10ABF0	Refrigerant pressure ,Below lower limit	Active/static

09 - Electronic central electric (9 DTCs)

DTC	Description	Status
B121D15	Left DRL bulb ,Circuit open or short to positive	Active/static
B121E15	Right DRL bulb ,Circuit open or short to positive	Active/static
B12E815	Left side marker lamp bulb ,Open circuit/short circuit to B+	Passive/Sporadic
B12E915	Right side marker lamp bulb ,Open circuit/short circuit to B+	Passive/Sporadic
B133A15	Left brake/tail lamp bulb ,Open circuit/short circuit to B+	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B18FBF0	Terminal 75 ,Limp home mode active	Passive/Sporadic
B131F54	Driver side rear window regulator ,No basic setting	Passive/Sporadic
B132054	Passenger side rear window regulator ,No basic setting	Passive/Sporadic

15 - Airbag (3 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B104B31	Key ,No signal	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
P1B0000	Generator mechanical fault	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

5F - Information electronics 1 (6 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B106713	Right rear bass speaker ,Open circuit	Active/static
B106213	Right front bass speaker ,Open circuit	Active/static
B106513	Left rear bass speaker ,Open circuit	Active/static
U111100	Function restriction caused by missing message	Passive/Sporadic

Technician Notes
2017324395

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.