Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZKU097989

Odometer Reading: 164346km
License Plate: JH31BTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	5
03 - Brakes 1	2
08 - Air conditioning	0
09 - Electronic central electric	10
15 - Airbag	2
17 - Instrument cluster	2
19 - Gateway	0
44 - Power steering	1
5F - Information electronics 1	3

DTC (25)

01 - Engine Control Module 1 (5 DTCs)

DTC	Description	Status
P305400	Starter does not turn ,Mechanically blocked or electrical malfunction	Active/static
P070400	Clutch switch input circuit	Passive/Sporadic
U100800	Data bus diagnostic interface ,Check event memory	Passive/Sporadic
P15A100	Transmission gear N sensor ,Signal implausible	Passive/Sporadic
P014C00	O2 Sensor Bank 1 Sensor 1 ,Slow Response - Rich to Lean	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C10A800	Wheel diameter implausible	Active/static

09 - Electronic central electric (10 DTCs)

DTC	Description	Status
B121715	Left low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B121815	Right low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B121E15	Right DRL bulb ,Circuit open or short to positive	Passive/Sporadic
B12E815	Left side marker lamp bulb ,Open circuit/short circuit to B+	Passive/Sporadic
B12CA15	License plate lamp ,Open circuit/short circuit to B+	Active/static
B147918	Remote control vehicle key 1 ,Insufficient current	Passive/Sporadic
B147A18	Remote control vehicle key 2 ,Insufficient current	Passive/Sporadic
B133029	Anti-theft alarm system sensor ,Range/performance	Passive/Sporadic
B14D1F5	Front driver window regulator ,Supply voltage below lower limit	Passive/Sporadic
B126A29	Lamp switch ,Range/performance	Active/static

15 - Airbag (2 DTCs)

DTC	Description	Status
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
B104B31	Key ,No signal	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
B126E13	Connection between radio and antenna amplifier 2 ,Open circuit	Active/static
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U11B800	Interface for external media ,No communication	Passive/Sporadic

Technician Notes

2017326456

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.