Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20260903123105
Test Time: 2026-09-03 12:31:05
Technician: Andrick

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/D-MAX/--
VIN: ACVTFR87JMD135626

Odometer Reading: 55147
License Plate: KXN963MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.61

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ECM(Engine Control Module)	0
ABS(Anti-lock Brake System)	4
SRS(Supplemental Restraint System)	0
IBS(Intelligent Battery System)	1
AT(Automatic Transmission)	0
DLU(Differential Lock Unit)	0
BCM(Body Control Module)	3
SCD(Speedometer Control Device)	0
WAM(Wireless Access Module)	2

DTC (10)

ABS(Anti-lock Brake System) (4 DTCs)

DTC	Description	Status
C0020_01	Pump motor electrical fault	Not present
C052E_49	Valve relay internal circuit fault	Not present
U0136_87	Lost communication with DLC	Not present
U1840_86	Invalid data received from BCM (stop lamp)	Not present

IBS(Intelligent Battery System) (1 DTC)

DTC	Description	Status
P058B_00	Current detection	Present

BCM(Body Control Module) (3 DTCs)

DTC	Description	Status
C172D_12	Left tail lamp output circuit short to battery	Not present

C0023_12	Stop lamp output circuit short to battery	Not present
B1707_11	Door lock/unlock output circuit short to ground	Not present

WAM(Wireless Access Module) (2 DTCs)

DTC	Description	Status
U0064_88	CAN communication fault (CAN bus off)	Not present
U0140_00	Lost communication with BCM	Not present

Technician Notes

2017293883

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.