Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260529125003
Test Time: 2026-05-29 12:50:03
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--
VIN: KMHJ3813MJU659445

Odometer Reading: 126167
License Plate: LV12JWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device information

Scanner: MaxiSys MS906 BT
Version: V14.05

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System		Status/DTC
ENG (Engine)		0
A/T (Transaxle)		0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)		0
AB (Airbag)		1
CLU (Cluster Module)		0
CODE (Transmitter Code Saving)		0
A/C (Air Conditioner)		0
EPS (Motor Driven Power Steering)		0
BCM (Body Control)		0
SMK (Smart Key Unit)		0
SJB (Smart Junction Block)		0
BSD-L (Blind Spot Detection-L)	ADAS	0
BSD-R (Blind Spot Detection-R)	ADAS	0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017245329

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.