Shop: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20240308132647
Test Time: 2024-03-08 13:26:47
Technician: Travino

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto/Morning (JA)/--
VIN: KNAB2511LNT842486
Odometer Reading: 55265km
License Plate: KF47XNGP

Customer Information

Name: MFC Dekra Nedbank Auction House
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.50
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(11)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	1
AB (Airbag)	2
CLU (Cluster Module)	0
I-TPMS (I-Tire Pressure Monitoring System)	1
A/C (Air Conditioner)	0
BCM (Body Control)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
RVM (Rear View Monitor) ADAS	0

DTC (5)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102:01	Battery voltage low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

I-TPMS (I-Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
C1102:01	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2016298521

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.