Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261110103636
Test Time: 2026-11-10 10:36:36
Technician: Barney

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Eritga/--
VIN: MA3BNC22S00826593

Odometer Reading: 147016
License Plate: LDP005MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	2
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	0
CGW(Central gateway control module)	0
EPS(Power steering)	0
BCM(Body Control Module)	0
SMK(Immobilizer and/or keyless system)	0

DTC (2)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1037	Steering angle sensor power supply voltage	History
C1057	Power supply voltage	History

Technician Notes

2017323397

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.