Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261111092544
Test Time: 2026-11-11 09:25:44
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--
VIN: MALAF51CLLM096247

Odometer Reading: 221580KM
License Plate: LM79BZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.15

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	2
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	0
AB (Airbag)	2
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

DTC (4)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0113:00	Intake air temperature (IAT) sensor 1 circuit input high	History
P0114:00	Intake air temperature (IAT) sensor 1 circuit intermittent	Active

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History

Technician Notes

2017324360

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.