Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261117142943
Test Time: 2026-11-17 14:29:43
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--
VIN: MALAF51CLNM164551
Odometer Reading: 154298KM
License Plate: MP15PYGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.15
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	0
AB (Airbag)	3
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

DTC (3)

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B1328:00	Driver front impact sensor (FIS) defect	History

Technician Notes

2017326416

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.