Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250304102644
Test Time: 2025-03-04 10:26:44
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51BLLM718020
Odometer Reading: 281501km
License Plate: JF37RLGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	0
ABS (Anti Lock Brake)	0
AB (Airbag)	2
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0

DTC (3)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1346:00	Driver airbag (DAB) resistance too high (1st Stage)	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102	Battery voltage low	History

Technician Notes

2016786593

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.