Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261102094921
Test Time: 2026-11-02 09:49:21
Technician: Barney

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Almera/--
VIN: MDHBBAN17Z0724714
Odometer Reading: 285044km
License Plate: KD26WCGP

Customer Information

Name: MFC Dekra
Tel: 0104120214

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (8)

System	Status/DTC
Engine	0
Transmission	0
ABS	1
Air bag	2
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	2
BCM	4
IPDM E/R	1

DTC (10)

ABS (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Air bag (2 DTCs)

DTC	Description	Status
B1049	Driver airbag module	Past
B1051	Driver airbag module	Past

Electric Power Steering (EPS)/DAST 3 (2 DTCs)

DTC	Description	Status
C1601	Battery VOLT	Past
U1000	CAN communication circuit	Past

BCM (4 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past

B2190	Nissan anti-theft system (NATS) antenna AMP	Past
B2191	Difference of key	Past
B2193	Chain of BCM-ECM	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

Technician Notes

2017320318

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.