Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250603105214
Test Time: 2025-06-03 10:52:14
Technician: Sbu

Proton VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Proton/Proton X50/--
VIN: PL1DG2FVRPG068456
Odometer Reading: 33747km
License Plate: LP51KTGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V2.50
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
EMS (Engine Management System)-Engine Management System (EMS) - China VI	0
ABS (AntiLock brake system)/ESP (Electronic stability program)	0
SRS (Supplement Restrain System)	0
IPK (Instrument panel system)-ICU (Instrument Control Unit)	0
BCM (Body Control Module)-BCM (Body Control Module)	3
EPS(Electronic Power Steering system)	1
MMI(Multimedia system)	0
A/C (automatic air conditioning system)	0

DTC (4)

BCM (Body Control Module)-BCM (Body Control Module) (3 DTCs)

DTC	Description	Status
U300616	ECU supply voltage low	History
B12A829	Start Stop Button (SSB) switched ON/OFF for 4 times continuously, and status of switch 1 and switch 2 inconsistent for 4 times	History
B12B216	Key 1 low battery	Current

EPS(Electronic Power Steering system) (1 DTC)

DTC	Description	Status

C113F93 Software calibration error - end learning not performed History

Technician Notes

2016900376

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.