Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CAPTUR/QM3/KABIN/--
VIN: VF12R5A1H53158782

Odometer Reading: 135892km
License Plate: HGR885FS

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
INJ(Injection)	3
ABS(Anti-lock braking system)	6
ABG(Airbag / pretensioners)	2
TDB(Instrument panel)	5
UCH(Central control unit)	9
DAV(Variable power assist steering)	3
UPC(Universal power controller)	14
UPA(Parking prox can) ADAS	0
RDO(Radio) ADAS	3
CLI(Air conditioning)	1
HFM(Hands-free module)	2

DTC (48)

INJ(Injection) (3 DTCs)

DTC	Description	Status
DTC013009	Upstream oxygen sensor circuit Component in poor condition.	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC1525F3	Consistent multiplex signals for CC/SL The data supplied to the cruise control or speed limiter are not correct.	Memory

ABS(Anti-lock braking system) (6 DTCs)

DTC	Description	Status

DTC403997	Rear right wheel target Component or system operation blocked or jammed	Memory
DTCC00100	Multiplexed network	Memory
DTCC10000	Injection multiplexed emission missing	Memory
DTCC12600	Steering wheel angle sensor multiplex signals	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

ABG(Airbag / pretensioners) (2 DTCs)

DTC	Description	Status
DTC80D224	Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer.	Memory
DTCF00316	Computer supply voltage Feed voltage too low	Memory

TDB(Instrument panel) (5 DTCs)

DTC	Description	Status
DTC94017B	Oil level sensor circuit Below the min level	Memory
DTC94037B	Brake fluid level circuit Below the min level	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH(Central control unit) (9 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated	Memory
DTC953018	Left indicator circuit	Memory
DTC953215	Alarm and/or motorised tailgate lin connection Open circuit or short circuit to +12 V	Memory
DTC954012	Rear interior lighting circuit Short-circuit to +12V	Memory
DTC956023	Start of clutch switch travel circuit	Memory

DTC956024	Start of clutch switch travel circuit	Memory
DTC956123	End of clutch switch travel circuit	Memory
DTC956223	Clutch pedal very start of travel sensor	Memory
DTC956224	Clutch pedal very start of travel sensor	Memory

DAV(Variable power assist steering) (3 DTCs)

DTC	Description	Status
DTCC10000	Injection multiplexed information missing No multiplex signal	Memory
DTCD00186	ABS multiplexed information invalid No multiplex signal	Memory
DTCF00313	Computer power supply Open circuit	Memory

UPC(Universal power controller) (14 DTCs)

DTC	Description	Status
DTC920F81	Upc-alternator link Invalid.	Memory
DTC921111	Battery disconnection unit Short circuit to earth.	Active
DTC921D11	Front wiper protection Short circuit to earth.	Memory
DTC922111	Rain/luminosity sensor circuit Short circuit to earth.	Active
DTC922181	Rain/luminosity sensor circuit Invalid.	Active
DTC922211	Steering column lock +APC circuit Short circuit to earth.	Memory
DTC922511	Power supply Short circuit to earth.	Memory
DTC923693	Rain/light sensor Failed	Active
DTC923696	Rain/light sensor Internal fault	Memory
DTC926681	12 V battery current sensor Communication disrupted	Active
DTC927094	Combined stalk under steering wheel circuit Performance down or incorrect operation	Memory
DTC928114	Battery voltage 12 V Open circuit or short circuit to earth	Memory

DTC928214	Battery voltage 12 V Open circuit or short circuit to earth	Memory
DTC928314	Battery voltage 12 V Open circuit or short circuit to earth	Memory

RDO(Radio) (3 DTCs)

DTC	Description	Status
DTC934149	Computer Internal electronic fault	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

CLI(Air conditioning) (1 DTC)

DTC	Description	Status
DTCF00316	Computer supply voltage Low voltage	Memory

HFM(Hands-free module) (2 DTCs)

DTC	Description	Status
DTCA0531C	Steering column lock +APC circuit	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes

2017296360

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.