



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20260320125118
Test Time: 2026-03-20 12:51:18
Technician: Travino

Audi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Audi/Audi A3/S3/RS3 2013>/--
VIN: WAUZZZ8V7F1036737

Odometer Reading: 169932km
License Plate: DX04GLGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.50

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (19)

System	Status/DTC
01 - Engine Control Module 1	 4
02 - Transmission electronics	 1
03 - Brakes 1	 5
08 - Air Conditioning	 5
09 - Electronic central electric	 6
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 1
19 - Gateway	 3
22 - All-wheel drive electronics	 0
42 - Driver's door electronics	 1
44 - Power steering	 1
52 - Passenger's door electronics	 1
55 - Headlamp range control	  0
5F - Information electronics 1	 2
76 - Parking aid	  3
A9 - Structure-Borne Sound Actuator	 2
BB - Rear drivers side door electronics	 1
BC - Rear passenger side door electronics	 4



**DTC (40)****01 - Engine Control Module 1 (4 DTCs)**

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic
P218300	Coolant temperature sensor 2 circuit range/performance	Passive/Sporadic
P001100	A Camshaft Position (Bank1) ,Timing over-advanced or System Performance	Passive/Sporadic

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P170100	Transmission control unit locked	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B116816	Steering angle sensor ,Voltage too low	Passive/Sporadic
C114602	TPMS ,Signal error	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic

08 - Air Conditioning (5 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B109171	Front air distribution flap motor ,Actuator stuck	Passive/Sporadic
B109915	Front air distribution flap motor potentiometer ,Circuit open or short to positive	Passive/Sporadic
B108B71	Fresh air recirculation, air flow flap motor ,Actuator stuck	Passive/Sporadic
B10CE00	Blower reduction by energy management	Passive/Sporadic

09 - Electronic central electric (6 DTCs)

DTC	Description	Status
B126301	Tank lid unlock activation ,Electrical error	Active/static
B140A4B	Central locking system ,Overtemperature	Passive/Sporadic
B12DD15	Rear lid Central Locking System Motor ,Open circuit/short circuit to B+	Active/static
B133029	Anti-theft alarm system sensor ,Range/performance	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system ,Voltage supply below lower limit	Passive/Sporadic
U112200	Data bus message implausible	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B104B31	Key ,No signal	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U140600	Static current ,too high	Passive/Sporadic
U141100	Battery terminal recognition ,Open circuit	Passive/Sporadic
P30DE00	Voltage drop via generator line too large	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

52 - Passenger's door electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

76 - Parking aid (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

A9 - Structure-Borne Sound Actuator (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

BB - Rear drivers side door electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

BC - Rear passenger side door electronics (4 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

B122B12	Central locking motors ,Circuit short to positive	Passive/Sporadic
B122B11	Central locking motors ,Circuit short to ground	Active/static
B122D29	Locking unit for central locking ,Range/performance	Active/static

Technician Notes
2017195355

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.