



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240725101239
Test Time: 2024-07-25 10:12:39
Technician: Andrick

Audi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Audi/Audi A3/S3/RS3 2013>/--
VIN: WAUZZZ8V9H1046818

Odometer Reading: 360460km
License Plate: FX25CKGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V21.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System	Status/DTC
01 - Engine Control Module 1	10
02 - Transmission electronics	3
03 - Brakes 1	3
08 - Air Conditioning	1
09 - Electronic central electric	4
15 - Airbag	1
16 - Steering column electronics	0
17 - Instrument cluster	1
19 - Gateway	2
42 - Driver's door electronics	1
44 - Power Steering	4
52 - Passenger's door electronics	1
5F - Information electronics 1	2
BB - Driver side rear door electronics	0
BC - Door Electronics Rear Passenger Side	1

DTC (34)

01 - Engine Control Module 1 (10 DTCs)

DTC	Description	Status
-----	-------------	--------



U112300	Databus error value received	Passive/Sporadic
P218500	Coolant temperature sensor 2 circuit high	Passive/Sporadic
U042800	Steering angle sensor Range/performance	Passive/Sporadic
P304400	Fuel pump Short circuit	Passive/Sporadic
P060C00	Internal control unit main processor performance	Passive/Sporadic
P055600	Brake booster pressure sensor circuit range/performance	Passive/Sporadic
P011700	Coolant temperature sensor 1 Circuit low	Passive/Sporadic
P001000	'A' Camshaft Position Actuator Circuit/Open (Bank1)	Passive/Sporadic
P060600	Ctrl. module faulty	Passive/Sporadic
P014800	Fuel Delivery Error	Passive/Sporadic

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
P17BF00	Hydraulic pump Play protection	Active/static
P17BF00	Hydraulic pump Play protection	Passive/Sporadic

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B1168F2	Steering angle sensor no initialization	Passive/Sporadic
C114201	Terminal 31 Electrical error	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
B10ABF0	Refrigerant pressure Below lower limit	Active/static

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
C108000	Left-/right hand driving switch-over active	Passive/Sporadic

B126301	Tank lid unlock activation Electrical error	Active/static
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
U10F300	Sirens / alarm horn for anti-theft warning system No communication	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B101A15	Driver frontal airbag crash sensor Circuit open or short to positive	Active/static

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B201000	No basic setting	Active/static

19 - Gateway (2 DTCs)

DTC	Description	Status
P1B0200	Battery monitoring control unit Faulty	Active/static
U141100	Battery terminal recognition Open circuit	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

44 - Power Steering (4 DTCs)

DTC	Description	Status
B1168F2	Steering angle sensor no initialization	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic

52 - Passenger's door electronics (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
-----	-------------	--------

U140000	Function restriction Caused by low voltage	Passive/Sporadic
B127213	Connection between antenna amplifier 1 and antenna Open circuit	Active/static

BC - Door Electronics Rear Passenger Side (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes

2016467650

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.