

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AM/AN - Golf Sports van 2014 >/--
VIN: WVWZZZAUZFW179186

Odometer Reading: 113732km
License Plate: FMG662L

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned(21)

System	Status/DTC
01 - Engine Control Module 1	 10
02 - Transmission electronics	 0
03 - Brakes 1	 5
08 - Air Conditioning	 3
09 - Electronic central electric	 2
14 - Wheel Damping Electronics	 0
15 - Airbag	 1
16 - Steering column electronics	 0
17 - Instrument cluster	 2
19 - Gateway	 2
20 - High beam assistant	 0
22 - All-wheel drive electronics	 0
2B - Steering Column Locking	 0
42 - Driver's door electronics	 1
44 - Power Steering	 1
52 - Passenger's door electronics	 2
55 - Headlight Regulation	 1
5F - Information electronics 1	 0

76 - Parking assistance

 1

A9 - Structure-Borne Sound Actuator

 1

B7 - Interface for access/start system

 0**DTC (32)****01 - Engine Control Module 1 (10 DTCs)**

DTC	Description	Status
P227100	O2 Sensor Signal Stuck Rich; Bank 1 Sensor 2	Passive/Sporadic
P200800	Intake Manifold Runner Bank 1 Control Circuit/Open	Active/static
P007000	Ambient Air Temperature Sensor Circuit	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
P055F00	Engine Oil Pressure Out of Range	Passive/Sporadic
P052400	Engine Oil Pressure Too Low	Passive/Sporadic
P06E900	Engine Starter Performance	Passive/Sporadic
P119A00	Fuel pressure sensor Malfunction	Passive/Sporadic
U042300	Invalid data received from Instrument cluster control unit	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B116816	Steering angle sensor Voltage too low	Passive/Sporadic
C114602	TPMS Signal error	Passive/Sporadic
C110029	Hydraulic assistance Range/performance	Passive/Sporadic
C1100F0	Hydraulic assistance not possible	Passive/Sporadic

08 - Air Conditioning (3 DTCs)

DTC	Description	Status
B108B71	Fresh air recirculation, air flow flap motor Actuator stuck	Active/static
U112300	Databus error value received	Passive/Sporadic

U112100	Data bus message missing	Passive/Sporadic
---------	--------------------------	------------------

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B103F1B	Exterior temperature sensor Resistance too high	Passive/Sporadic
B126301	Tank lid unlock activation Electrical error	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111000	Function restriction caused by communication interruption	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U105400	Information electronics 1 control unit No communication	Passive/Sporadic
U140600	Static current too high	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B132601	Door warning light Electrical error	Active/static

44 - Power Steering (1 DTC)

DTC	Description	Status
C10D700	Comfort restriction	Passive/Sporadic

52 - Passenger's door electronics (2 DTCs)

DTC	Description	Status
B148713	Motor for window regulator Open circuit	Active/static
B132601	Door warning light Electrical error	Active/static

55 - Headlight Regulation (1 DTC)

DTC	Description	Status
-----	-------------	--------

C108413

Right stationary AFS
Open circuit

Active/static

76 - Parking assistance (1 DTC)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic

A9 - Structure-Borne Sound Actuator (1 DTC)

DTC	Description	Status
U10D900	Incorrect vehicle type	Active/static

Technician Notes

2016322130

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.