



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240923084619
Test Time: 2024-09-23 08:46:19
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >/--
VIN: WVVZZZAUZHWO51905

Odometer Reading: 229016km
License Plate: N o r e g

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V21.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(12)

System	Status/DTC
01 - Engine Control Module 1	 19
03 - Brakes 1	 7
08 - Air Conditioning	 3
09 - Electronic central electric	 7
15 - Airbag	 0
16 - Steering column electronics	 0
17 - Instrument cluster	 2
19 - Gateway	 2
42 - Driver's door electronics	 2
44 - Power Steering	 6
52 - Passenger's door electronics	 2
5F - Information electronics 1	 4

DTC (54)

01 - Engine Control Module 1 (19 DTCs)

DTC	Description	Status
P164D00	Reduced oil pressure switch Fault	Passive/Sporadic
P308800	Starter relay Electrical fault in circuit	Passive/Sporadic



>

P305400	Starter does not turn Mechanically blocked or electrical malfunction	Passive/Sporadic
U112300	Databus error value received	Active/static
P16BA00	Charge pressure cooler coolant pump Dry run	Passive/Sporadic
P15A100	Transmission gear N sensor Signal implausible	Passive/Sporadic
U042800	Steering angle sensor Range/performance	Passive/Sporadic
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic
P060C00	Internal control unit main processor performance	Active/static
P011700	Coolant temperature sensor 1 Circuit low	Passive/Sporadic
P034100	Camshaft Position (CMP) sensor circuit Range/performance	Passive/Sporadic
P102000	Fuel Pressure Regulation Control limit exceeded	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P030200	Cylinder 2 Misfire detected	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static
P157000	Engine control unit disabled	Passive/Sporadic
P125000	Fuel level too low	Active/static

03 - Brakes 1 (7 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B1168F2	Steering angle sensor no initialization	Active/static
C10E129	Parking brake motors Range/performance	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

C114602	TPMS Signal error	Passive/Sporadic
C114513	Button lamp for electrical parking brake Open circuit	Active/static
C10E1F0	Parking brake motors Opened insufficiently	Passive/Sporadic

08 - Air Conditioning (3 DTCs)

DTC	Description	Status
B109D71	Air distribution door servomotor Actuator stuck	Active/static
B10CE00	Blower reduction by energy management	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (7 DTCs)

DTC	Description	Status
B122015	Right fog lamp bulb Circuit open or short to positive	Active/static
B12CA15	License plate lamp Open circuit/short circuit to B+	Active/static
B12CA01	License plate lamp Electrical error	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B147A18	Remote control key 2 Voltage too low	Active/static
B1330F5	Anti-theft alarm system sensor Alert - emergency activation stage 1	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

U141100	Battery terminal recognition Open circuit	Active/static
---------	--	---------------

42 - Driver's door electronics (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B148754	Motor for window regulator No basic setting	Active/static

44 - Power Steering (6 DTCs)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
P160200	Power supply terminal 30 Voltage too low	Passive/Sporadic
B1168F2	Steering angle sensor no initialization	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic

52 - Passenger's door electronics (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B148754	Motor for window regulator No basic setting	Passive/Sporadic

5F - Information electronics 1 (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B106713	Right rear bass speaker Open circuit	Active/static
B106513	Left rear bass speaker Open circuit	Active/static

Technician Notes

2016542928

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.