

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AM/AN - Golf Sports van 2014 >/--
VIN: WVWZZZAUZHW179765

Odometer Reading: 221224km
License Plate: KSZ710MP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50

Serial Number: VB8GJCC01509
Repair Order Number: --



System Scanned(18)

System	Status/DTC
01 - Engine Control Module 1	6
02 - Transmission electronics	3
03 - Brakes 1	7
08 - Air Conditioning	2
09 - Electronic central electric	8
15 - Airbag	0
16 - Steering column electronics	0
17 - Instrument cluster	3
19 - Gateway	4
2B - Steering Column Locking	1
42 - Driver's door electronics	4
44 - Power Steering	4
47 - Sound system	1
52 - Passenger's door electronics	3
55 - Headlight Regulation	5
5F - Information electronics 1	1
A9 - Structure-Borne Sound Actuator	0
B7 - Interface for access/start system	1

**DTC (53)****01 - Engine Control Module 1 (6 DTCs)**

DTC	Description	Status
U030000	Control module Software incompatible	Active/static
P019000	Fuel Rail Pressure Sensor 'A' Circuit	Active/static
U041600	Invalid data received from vehicle dynamics control module	Active/static
P034000	Camshaft Position Sensor Circuit	Active/static
U013100	Lost communication with power steering control unit	Passive/Sporadic
U044700	Invalid data received from serial data gateway module A	Passive/Sporadic

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
P177B00	Clutch 1 Tolerance limit reached	Active/static
U010300	Lost communication with gear shift module	Passive/Sporadic
U013100	Lost communication with power steering control unit	Passive/Sporadic

03 - Brakes 1 (7 DTCs)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B116831	Steering angle sensor No signal	Passive/Sporadic
B1168F2	Steering angle sensor no initialization	Active/static
U112100	Data bus message missing	Active/static
U112100	Data bus message missing	Passive/Sporadic
C114602	TPMS Signal error	Passive/Sporadic
C114513	Button lamp for electrical parking brake Open circuit	Passive/Sporadic

08 - Air Conditioning (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (8 DTCs)

DTC	Description	Status
B12ECF2	LED module for left DRL and parking lamp Power supply circuit open or short to positive	Active/static
B12EDF2	LED module for right DRL and parking lamp Power supply circuit open or short to positive	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B140B29	Release button in trunk lid handle Range/performance	Passive/Sporadic
B1330F5	Anti-theft alarm system sensor Alert - emergency activation stage 1	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic
B128104	Humidity sensor Faulty	Active/static

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U112100	Data bus message missing	Active/static
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U101D00	Lost communication with power steering control unit	Passive/Sporadic
U013900	Lost communication with suspension control unit B	Active/static
U105200	Generator No communication	Passive/Sporadic
C115531	Analog measurement input No signal	Active/static

2B - Steering Column Locking (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

42 - Driver's door electronics (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

B122D29	Locking unit for central locking Range/performance	Active/static
B177501	Door warning light / entry light Electrical error	Active/static
B131FF5	Driver side rear window regulator Voltage supply below lower limit	Passive/Sporadic

44 - Power Steering (4 DTCs)

DTC	Description	Status
B1168F2	Steering angle sensor no initialization	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic
B202000	Function limitation through missing initialization	Passive/Sporadic

47 - Sound system (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

52 - Passenger's door electronics (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B177501	Door warning light / entry light Electrical error	Active/static
B1320F5	Passenger side rear window regulator Voltage supply below lower limit	Passive/Sporadic

55 - Headlight Regulation (5 DTCs)

DTC	Description	Status
C1081F0	Left headlamp power output stage Not coded	Active/static
C108131	Left headlamp power output stage No signal	Active/static
U112100	Data bus message missing	Active/static
U112200	Data bus message implausible	Active/static
U112100	Data bus message missing	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
-----	-------------	--------

U140000

Function restriction
Caused by low voltage

Passive/Sporadic

B7 - Interface for access/start system (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes

2016331714

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.