DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park -**
Requested Date	**11/12/2025**		
Inspection Date	**11/12/2025**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**FORD**	Registration Number	**KLD905NW**
Model	**FIGO 1.5 TITANIUM 5-DR [2018-2021]**	Register Number	
VIN	**MAJGXXMTKGLK68424**	Date Of First Licensing	
Engine Number		Last COR	
Doors	**5**	License Expiry Date	**31/10/2025**
Color	**SILVER**	Power / Displacement	
Year Model	**2021**	Paint Finish	**TWO COAT UNI**
Km Reading	**111,906 KM**	Fuel	**PETROL**
Cab / Body Type	**HATCHBACK**	Transmission	**MANUAL**

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025





Damage	Repair Way
Engine Wiring Defective	Repair
Caps Missing	Replace
Expansion Bottle Water Leak	Replace
Radiator Damaged	Replace
Air conditioner pipes Damaged	Replace
Air Conditioner Insufficient	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Boot Carpet Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Windscreen Cracked	Replace
Caliper 1. Axle left Leak	Repair
Wheel bearing Front Left Loose / Excessive Play	Replace
Rear Axle Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Rear Left Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Main Beam Left Damaged	Repair
Gearbox Mountings Cracked	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Repair
Gear Selections Insufficient	Repair
Jack Missing	Replace
Road test	Gearbox faulty
Electrical instruments and components	Ignition malfunction
Warning lights illuminated on dashboard	Repair
Engine	Aircon condenser missing
Engine	Engine fan malfunction
Undercarriage	Clutch slave leaking
Body and Exterior	Front bumper stiffener damaged
Body and Exterior	Front right chassis leg extension damaged
Tyres and rims	Spare wheel missing.
Electrical instruments and components	Speedometer not working.
Tyres and rims	Front and rear tyre sizes different.
Vehicle electronics malfunction	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No: 2017099164
DATE 11/12/2025

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.8	2.14	-	
Rear	1.78	1.81	-	
Emergency / Parking	0.98	1.23	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65 R15	91V	Dunlop	Sp-Sport	V	2222	0 mm
Front Right	185/60 R15	84H	Sumitomo	HTR H5	V	0822	0 mm
Rear Left	165/80 R13	83T	Blackhawk	Street-H	V	3420	1 mm
Rear Right	195/55 R15	85V	Goodyear	Eagle	V	4815	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	P0217:00-68	ENGINE COOLANT OVER TEMPERATURE CONDITION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Brake booster reservoir cap missing.
Interior: Vehicle interior dirty and some panels scratched
Body • Exterior: Dents and scratches on some body panels.Signs of impact damage to front of vehicle.Some body panels misaligned
Undercarriage: Non standard bolts fitted to gearbox.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase
DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424


DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025




Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



LICENSE DISC



VIN PLATE OR STICKER


ENGINE 1


Front chassis


Rear chassis


Front bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Front right chassis leg extens



Oil cap and dipstick



Clutch slave



Side Mirror Right



Front Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Door Rear Right



Rear Fender Right



Sill Panel Right



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Rear Fender Left



Rear Fender Left



Door Front Left



Door Front Left



Sill Panel Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Front Fender Left



Windscreen



Front Bumper



Front Bumper



Bonnet



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Headlight Right



Headlight Left



Air Conditioner



Boot Carpet



Caps



Expansion Bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Bonnet slam plate (Shock tower/ Inner tray)



Engine Wiring



Bolt(s) / Nut(s) Front Wheel Right



Engine Wiring



Radiator Cradle



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Engine Wiring



Rim Rear Left



Tyre Rear Left



Engine Wiring



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



CV Joint(s) Boot(s) Front Left (inner/outer)



Wheel bearing Front Left



Main Beam Left



Tyre Front Right



Tyre Front Left



Caliper 1. Axle left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Radiator Cradle



Air conditioner pipes



CV Joint(s) Boot(s) Front Right (inner/outer)



Tyre Rear Right



Rear Axle



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424

DEKRA

CONDITION REPORT

Report No:
2017099164
DATE
11/12/2025



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJGXXMTKGLK68424