CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	11/11/2026		
Inspection Date	11/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	HW56DTGP
Model	I20 1.4 FLUID 5-DR AT [2018-2021]	Register Number	
VIN	MALBM51CMKM634073	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2027
Color	SILVER	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT UNI
Km Reading	314,148 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026





Damage	Repair Way
Engine Oil Leak	Repair
Radio/CD/USB Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Loose / Excessive Play	Repair
Hood Lining Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Damaged	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Roof Dented	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Steering Noisy	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.6	3.08	-	
Rear	2.21	1.88	-	
Emergency / Parking	1.64	1.35	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55 R16	87V	Yokohama	Bluearth	V	2624	3 mm
Front Right	195/55 R16	87V	Yokohama	Bluearth	V	2724	3 mm
Rear Left	195/55 R16	87V	Yokohama	Bluearth	V	2724	3 mm
Rear Right	195/55 R16	87V	Yokohama	Bluearth	V	2624	3 mm
Spare	195/55 R16	87V	Bridgestone	B250	V	3818	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Radio malfunction
Lights: Front left and right headlight lenses faded.
Interior: Vehicle interior dirty and panels scratched.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Front chassis




Rear chassis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT


Report No:
2017324443
DATE
11/11/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



VIN PLATE OR STICKER



LICENSE DISC



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Radio/CD/USB



Seat Front Right



Door Sealing Rubber Front Right



Seat Rear



Rear Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT


Report No:
2017324443
DATE
11/11/2026



Door Front Right




Door Rear Right



Front Fender Right



Bonnet



Front Fender Left



Door Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Door Rear Left



Rear Fender Left



Seat Front Left



Center Console / Cubbyhole + Lid



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Boot Lid / Hatch door



Roof



Headlight Right



Headlight Left



Control Arm Bush(es) Front Axle Right



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Rim Rear Left



Control Arm Bush(es) Front Axle Left



Front Fender Left / Inner Tray



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Sill Panel Right



Gearbox



Engine



CV Joint(s) Boot(s) Front Left (inner/outer)



Mounting Rubber(s) Rear Axle Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073

DEKRA

CONDITION REPORT

Report No:
2017324443
DATE
11/11/2026



Hood Lining



Center Console / Cubbyhole + Lid



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CMKM634073