DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	02/11/2026		
Inspection Date	02/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	NISSAN	Registration Number	KD26WCGP
Model	ALMERA 1.5 ACENTA AT [2016-2024]	Register Number	
VIN	MDHBBAN17Z0724714	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2018	Paint Finish	C - COMMON
Km Reading	285,044 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Indicator Light Front Left Damaged	Replace
Tail Light Right Cracked	Replace
Dim Light Right Defective	Replace
Brake Light Right Defective	Replace
Seat Front Right Worn	Repair
Door Sealing Rubber Front Right Torn / Cut	Replace
Dash Padding Damaged	Repair
Steering Wheel Trim Damaged	Repair
Side Mirror Left Deformed	Replace
Front Bumper Damaged	Repair
Bonnet Paintwork • Discoloured	Repair
A • Pillar Left Dented	Repair
A • Pillar Right Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Residual Traces of Repair	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Dented	Repair
Roof Dented	Repair
Shock Absorber Rear Left Leak	
Shock Absorber Rear Right Leak	Replace
Shock Absorber Mounting Front Left Cracked	Replace
Shock Absorber Mounting Front Right Cracked	Replace
Ball Joint(s) Front Axle Left Damaged	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Smooth	Replace
Chassis Dented	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Radiator Cradle Damaged	Repair
CHASIS LEG EXTENSION	Damaged needs replacement
Warning lights	Airbag light illuminated
REAR TYRES	Sizes differs

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.6	2.5	-	
Rear	1.7	1.9	-	
Emergency / Parking	1.4	1.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60R15	88V	INVOVIC	EL601	V	2225	3 mm
Front Right	195/60R15	88V	INVOVIC	EL601	V	4025	3 mm
Rear Left	195/60R15	88H	WINDFORCE	CATCHFORS PC	V	3922	1 mm
Rear Right	195/65R15	91V	GOODYEAR	EAGLE NCT 5	V	2005	1 mm
Spare	185/65R15	88H	FALKEN	SINCERA	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	U1000	CAN COMMUNICATION CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.Body • Exterior: The body has traces of poor residual repairs on some body panels below standard.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714


DEKRA

CONDITION REPORT


Report No:
2017320318
DATE
02/11/2026




DIAGNOSTICS



DIAGNOSTICS



BRAKE REPORT



OIL CAP AND DIPSTICK



Battery



Windscreen wiper bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Chasis leg extension



SPAREWHEEL



Warning light



AUTOMATIC



CHASIS



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026




90 DEGREE REAR



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



LICENSE DISC



VIN PLATE OR STICKER



CHASSIS



ENGINE 1



ENGINE 2



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Front Bumper


Front Bumper


Front Bumper



Front Bumper


Front Bumper


Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714


DEKRA

CONDITION REPORT

Report No: 2017320318
DATE 02/11/2026


Tyre Rear Right


Ball Joint(s) Front Axle Left


Engine


Gearbox


Belly plates


Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Chassis



Front Fender Left / Inner Tray



Front Fender Left / Inner Tray



Radiator Cradle



Front Bumper



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Sill Panel Right




Radiator Cradle



Shock Absorber Rear Right



Shock Absorber Rear Left



Front Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Rear Fender Left



Front Fender Left



Door Front Left



Door Rear Left



Sill Panel Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Rear bumper



Rear bumper



Rear bumper



Door Rear Right



Door Front Right



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Rear Fender Left



Rear Fender Right



Boot Lid / Hatch door



Boot Lid / Hatch door



Boot Lid / Hatch door



A • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



A • Pillar Left



Roof



Shock Absorber Mounting Front Right



Shock Absorber Mounting Front Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Bonnet



Door Sealing Rubber Front Right



Seat Front Right



Dash Padding



Steering Wheel Trim



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714

DEKRA

CONDITION REPORT

Report No:
2017320318
DATE
02/11/2026



Tail Light Right



Dim Light Right



Brake Light Right



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MDHBBAN17Z0724714