DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	05/11/2026		
Inspection Date	05/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	FRV817L
Model	CLIO IV 0.9 TURBO EXPRESSION 5-DR [2013-2017]	Register Number	
		Date Of First Licensing	
VIN	VF15R5A0H51344557	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	M - METALLIC
Year Model	2015	Fuel	PETROL
Km Reading	176,860 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Damaged	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Shock Left Defective	Replace
Boot Lid / Hatch Door Shock Right Defective	Replace
Rear bumper Dented	Repair
Belly plates Damaged	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Body exterior	Vehicle got some scratches, stone chips and dents
Battery light on	Repair
Service light on	Repair
Both front fog lights malfuntion	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.0	2.8	-	
Rear	1.5	1.5	-	
Emergency / Parking	1.1	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	87H	Sailun	Atrezzo	V	4824	3 mm
Front Right	195/55R16	87H	Sailun	Atrezzo	V	4423	3 mm
Rear Left	195/55R16	91V	Durun	Hg918	V	1924	3 mm
Rear Right	195/55R16	91V	Durun	Hg918	V	4723	3 mm
Spare	185/65R15	88T	Barum	Brilliants	V	1714	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MEMORY	DTC011517	WATER TEMPERATURE SENSOR CIRCUIT VOLTAGE TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026



Shock and brake report



Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



Manual

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026



Expention bottle



Oil cap and dipstick



Spare wheel



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557


DEKRA

CONDITION REPORT


Report No:
2017321636
DATE
05/11/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026




ENGINE 1



ENGINE 2



CHASSIS



Seat Front Right



Water level



Bonnet


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026



Boot Lid / Hatch Door Shock Left



Boot Lid / Hatch Door Shock Right



Boot Lid / Hatch door



Rear bumper



Rear bumper



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT


Report No:
2017321636
DATE
05/11/2026



Door Front Right



Rear Fender Right



Front Fender Right



Side Mirror Right



Front Bumper



Grill


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT


Report No:
2017321636
DATE
05/11/2026




Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Belly plates



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557

DEKRA

CONDITION REPORT

Report No:
2017321636
DATE
05/11/2026



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15R5A0H51344557