



Shop: Dekra MFC
Tel: 0861033572
Email: --
Address: MFC Auction House
M57 Pretoria Road
Glen Marais
Kempton Park
1619

Report ID: MAXIA20231208094651
Test Time: 2023-12-08 09:46:51
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU017670

Odometer Reading: 30019
License Plate: N o n e n u m b e r p l a t e













Customer Information

Name: MFC MFC
Tel: 0000

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(12)

System	Status/DTC
01 - Engine Control Module 1	 6
03 - Brakes 1	 2
04 - Steering Angle Sender	 1
08 - Air Conditioning	 2
09 - Electronic central electric	 2
15 - Airbag	 1
17 - Instrument cluster	 1
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 1
56 - Radio	 1
61 - Battery Regulation	 0

DTC (17)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P160900	Crash shutoff triggered	Passive/Sporadic



P307300	Fuel pump Electrical error in circuit	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P125000	Fuel level too low	Active/static

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C102D00	Tire pressure warning	Passive/Sporadic
C102D00	Tire pressure warning	Active/static

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

08 - Air Conditioning (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

Technician Notes

2016194485

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.