



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250214132153
Test Time: 2025-02-14 13:21:53
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: AAVZZZAWZKU080003

Odometer Reading: 97314km
License Plate: KDR542MW

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	 9
03 - Brakes 1	 2
08 - Air Conditioning	 1
09 - Electronic central electric	 10
15 - Airbag	 1
17 - Instrument cluster	 3
19 - Gateway	 3
44 - Power Steering	 1
5F - Information electronics 1	 3

DTC (33)

01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
U100800	Diagnostic interface for data bus Read out DTC	Passive/Sporadic
P151B00	Voltage terminal 15 Implausible	Passive/Sporadic
U043100	Invalid data received from body control module A	Passive/Sporadic
P036600	Camshaft Position (CMP) sensor circuit Range/performance	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static



P014800	Fuel Delivery Error	Passive/Sporadic
P125000	Fuel level too low	Active/static
P007200	Ambient air temperature sensor circuit Low	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic
C102D00	Tire pressure warning	Active/static

08 - Air Conditioning (1 DTC)

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

09 - Electronic central electric (10 DTCs)

DTC	Description	Status
B12E915	Right side marker lamp bulb Open circuit/short circuit to B+	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system Voltage supply below lower limit	Passive/Sporadic
B132329	Driver side rear power window button Range/performance	Passive/Sporadic
B13214B	Driver side rear window regulator motor Overtemperature	Passive/Sporadic
B132429	Passenger side rear window regulator button Range/performance	Passive/Sporadic
B14D34B	Driver side front window regulator motor Overtemperature	Passive/Sporadic
B131529	Driver side window regulator control unit Range/performance	Passive/Sporadic
B14D44B	Front passenger side window regulator motor Overtemperature	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
-----	-------------	--------

B13BCF2	Multiple collision brake No function	Passive/Sporadic
---------	---	------------------

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U141100	Battery terminal recognition Open circuit	Active/static

44 - Power Steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
U140100	Function restriction Caused by excessive voltage	Passive/Sporadic
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B106713	Right rear bass speaker Open circuit	Active/static

Technician Notes
2016762955

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.