AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240222113334 Test Time: 2024-02-22 11:33:34

Technician: Andrick

Page 1

## Volkswagen VEHICLE DIAGNOSTIC REPORT

**Vehicle Information** 

--/Volkswagen/AW/C1 - T-Cross 2019 >/--

VIN: AAVZZZAWZLU025604

**Customer Information** 

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V19.00

Odometer Reading: 152336km License Plate: JL07CVGP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

## 🔁 System Scanned( 10 )

| System                           | Status/DTC |
|----------------------------------|------------|
| 01 - Engine Control Module 1     | <b>Q</b> 5 |
| 02 - Transmission electronics    | <b>Q</b> 4 |
| 03 - Brakes 1                    | <b>Q</b> 4 |
| 08 - Air Conditioning            | <b>②</b> 0 |
| 09 - Electronic central electric | <b>Q</b> 7 |
| 15 - Airbag                      | <b>Q</b> 2 |
| 17 - Instrument cluster          | <b>Q</b> 1 |
| 19 - Gateway                     | <b>Q</b> 3 |
| 44 - Power Steering              | <b>Q</b> 1 |
| 5F - Information electronics 1   | <b>②</b> 0 |

## **DTC (27)**

## 01 - Engine Control Module 1 (5 DTCs)

| DTC     | Description  | Status           |
|---------|--|------------------|
| U041600 | Invalid data received from vehicle dynamics control module       | Passive/Sporadic |
| P168200 | Powertrain data bus<br>Implausible message from ABS control unit | Passive/Sporadic |
| P050700 | Idle control system<br>Speed higher than specified value         | Passive/Sporadic |
| P227900 | Intake air system leakage  | Passive/Sporadic |

AUTEL www.autel.com

MaxiSys MS906 BT

| /Volkswagen/A\  | N/C1 - T-Cross 2019 > Test Time: 2024-02-22 11:33:34                                | Report ID: MAXIA20240222113334 |
|-----------------|---|--------------------------------|
| P068B00         | ECM/PCM Power Relay De-Energized Performance - Too<br>Late                          | Passive/Sporadic               |
| 02 - Transmis   | ssion electronics ( 4 DTCs )  |                                |
| DTC             | Description   | Status                         |
| P177B00         | Clutch 1<br>Tolerance limit reached   | Passive/Sporadic               |
| P189A00         | Clutch 1<br>Clearance too small   | Passive/Sporadic               |
| P056200         | System Voltage<br>Low Voltage   | Passive/Sporadic               |
| U010300         | Lost communication with gear shift module   | Passive/Sporadic               |
| 03 - Brakes 1   | (4DTCs)   |                                |
| DTC             | Description   | Status                         |
| C106A16         | ABS valves voltage supply<br>Voltage too low  | Passive/Sporadic               |
| U140000         | Function restriction Caused by low voltage  | Passive/Sporadic               |
| U016700         | Lost Communication With Vehicle Immobilizer Control<br>Module                       | Passive/Sporadic               |
| C10A416         | Low pressure sensor power supply<br>Voltage too low                                 | Passive/Sporadic               |
| 09 - Electroni  | c central electric (7 DTCs)   |                                |
| DTC             | Description   | Status                         |
| B11EB15         | Right rear turn signal bulb<br>Open circuit/short circuit to B+                     | Passive/Sporadic               |
| B133C15         | Right brake/tail lamp bulb<br>Open circuit/short circuit to B+                      | Passive/Sporadic               |
| U101100         | Supply voltage<br>Voltage too low   | Passive/Sporadic               |
| U12AE00         | Switching off control modules by knockout meter                                     | Passive/Sporadic               |
| B131DF5         | Sirens/alarm horn for anti-theft warning system<br>Voltage supply below lower limit | Passive/Sporadic               |
| B116229         | Gear selector lever park position lock switch Range/performance                     | Passive/Sporadic               |
| B11F129         | Front passenger side window regulator button Range/performance                      | Active/static                  |
| 15 - Airbag ( 2 | 2 DTCs)   |                                |
| DTC             | Description   | Status                         |
|                 |   |                                |

AUTEL www.autel.com MaxiSys MS906 BT Page 2

| /Volkswagen/AV                 | V/C1 - T-Cross 2019 >                   | Test Time: 2024-02-22 11:33:34 | Report ID: MAXIA20240222113334 |
|--------------------------------|---|--------------------------------|--------------------------------|
| B13BCF2                        | Multiple collision brake<br>No function |                                | Passive/Sporadic               |
| U101100                        | Supply voltage<br>Voltage too low       |                                | Passive/Sporadic               |
| 17 - Instrume                  | nt cluster ( 1 DTC )                    |                                |                                |
| DTC                            | Description                             |                                | Status                         |
| U101100                        | Supply voltage<br>Voltage too low       |                                | Passive/Sporadic               |
| 19 - Gateway                   | (3DTCs)                                 |                                |                                |
| DTC                            | Description                             |                                | Status                         |
| U101100                        | Supply voltage<br>Voltage too low       |                                | Passive/Sporadic               |
| U140600                        | Static current<br>too high              |                                | Passive/Sporadic               |
| B1802F1                        | NV-Energy management<br>Alarm triggered |                                | Passive/Sporadic               |
| 44 - Power St                  | eering ( 1 DTC )                        |                                |                                |
| DTC                            | Description                             |                                | Status                         |
| B200FF0                        | Internal malfunction                    |                                | Passive/Sporadic               |
| <b>Technician N</b> 2016277891 | lotes                                   |                                |                                |

| Customer name: |  |
|----------------|--|
| Technician:    |  |
| Data           |  |

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

