



Shop: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20240408084137
Test Time: 2024-04-08 08:41:37
Technician: Andrick

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVMRRAR4L4093798

Odometer Reading: 53303
License Plate: FVG261L

Customer Information

Name: MFC Dekra Nedbank Auction House




Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(4)

System	Status/DTC
SRS	 7
SRS (Denso)	 7
Immobilizer	 0
Meter	 0

DTC (14)

SRS (7 DTCs)

DTC	Description	Status
B00120D	Driver airbag circuit high resistance	Present
B00150D	Driver pretensioner circuit high resistance	Present
B00190D	Passenger airbag circuit high resistance	Present
B00220D	Passenger pretensioner circuit high resistance	Present
B005200	Airbag circuit activated (crash)	Present
B005202	Pretensioner circuit activated (crash)	Present
B008439	Right front airbag sensor disconnected	Not present

SRS (Denso) (7 DTCs)

DTC	Description	Status
B00120D	Driver airbag circuit high resistance	Present
B00150D	Driver pretensioner circuit high resistance	Present
B00190D	Passenger airbag circuit high resistance	Present
B00220D	Passenger pretensioner circuit high resistance	Present
B005200	Airbag circuit activated (crash)	Present



B005202	Pretensioner circuit activated (crash)	Present
B008439	Right front airbag sensor disconnected	Not present

Technician Notes

2016331658

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.