

Shop: --Tel: --Email: --Address: --

## Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information	
/Isuzu/TF series/D-MAX/	Odometer Reading: 96547
VIN: ADMNRCHR4H4825370	License Plate: KMK001NW
Customer Information	
Name: MFC Dekra Nedbank Auction House	Tel: 0861033572
Device information	
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01509
Version: V5.30	Repair Order Number:
System Scanned( 6 )	
System Scanned( 6 )	

## System Scanned( 6)

System	Status/DTC
4JK1	<b>O</b>
ABS/ESC	<b>Q</b> 1
SRS	📀 0
SRS (Denso)	📀 0
Immobilizer	📀 0
Meter	🕑 0

## 🔼 DTC (1) ABS/ESC (1 DTC)

DTC	Description	Status
C004506	Left rear wheel speed sensor (WSS) circuit fault	Present

## **Technician Notes**

2016309496

Customer name:

Technician: \_\_\_\_\_

Date: \_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

