



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250627152257
Test Time: 2025-06-27 15:22:57
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTJB8DDX04755825

Odometer Reading: 109927
License Plate: JPG682MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine and ECT	2
ABS/VSC/TRC	2
SRS airbag	0
Combination meter	0
Cruise control	0
4WD	1
Navigation system	2

DTC (7)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1604	Startability fault	History
P1605	Rough idling	History

ABS/VSC/TRC (2 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
U0114	Lost communication with 4WD clutch control module	History

4WD (1 DTC)

DTC	Description	Status
P17C0	Rear differential lock solenoid circuit low	History

Navigation system (2 DTCs)

DTC	Description	Status
-----	-------------	--------



U0100	Engine/EV ECU communication	History
C1622	Rear camera disconnected	History

Technician Notes
2016927884

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.