



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250620115441
Test Time: 2025-06-20 11:54:41
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P507157266

Odometer Reading: 186631km
License Plate: HCN956L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	0
ABS/VSC/TRC	4
SRS airbag	2
Combination meter	1
Immobilizer	0

DTC (7)

ABS/VSC/TRC (4 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1290	Zero point of wheel speed sensor (WSS) abnormal	Current
C1290	Zero point of wheel speed sensor (WSS) abnormal	History
C1425	Stop switch circuit open	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
B1508	Turn signal/hazard flasher circuit short	History

Technician Notes
2016919327



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.