AUTEĽ

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20231221153018 Test Time: 2023-12-21 15:30:18

Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--VIN: AHTSS22P907150062

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

P squib circuit open

Device information

Scanner: MaxiSys MS906 BT

Version: V9.10

Odometer Reading: 25419km License Plate: DCH510NC

Tel: 0861033572

Serial Number: VB8GJCC01482

History

Repair Order Number: --

🔁 System Scanned(5)

System	Status/DTC	
Engine and ECT	◎ 0	
ABS/VSC/TRC	Q 1	
SRS airbag	Q 2	
Combination meter	◎ 0	
Immobilizer	② 0	
_		

🔼 DTC (3)

B1806

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
SRS airbag	(2 DTCs)	
DTC	Description	Status
B1801	Driving side squib circuit open	History

www.autel.com MaxiSys MS906 BT Page 1

Toyota/ Hiace/Ventury/	Test Time	2023-12-21 15:30:18	Report ID:	MAXIA20231221153018
10yota/ 11lace/ veritury/	i cot i iiiic.	2023-12-21 13.30.10	neport ib.	MAXIAZUZJIZZIIJJUIC

Technician Notes

2016209474

Customer name: _	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2