

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSX22PX07036993

Odometer Reading: 307724km
License Plate: KG64KXGP

Customer Information

Name: MFC Dekra Nedbank Auction House








Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.21

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine and ECT	 3
ABS/VSC/TRC	 2
SRS airbag	 4
Combination meter	 3
Cruise control	  0
Immobilizer	 0

DTC (12)

Engine and ECT (3 DTCs)

DTC	Description	Status
P0016	Crankshaft position (CKP)/Camshaft position (CMP) correlation (bank 1 sensor A)	Pending
P0016	Crankshaft position (CKP)/Camshaft position (CMP) correlation (bank 1 sensor A)	Current
P0016	Crankshaft position (CKP)/Camshaft position (CMP) correlation (bank 1 sensor A)	History

ABS/VSC/TRC (2 DTCs)

DTC	Description	Status
C0278	ABS solenoid relay circuit open	Current
C1241	Low or high power supply voltage	Current

SRS airbag (4 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current

B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History
B1906	Pretensioner squib (left) circuit open	History

Combination meter (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0129	Lost communication with brake system control module	History
B1507	Turn signal circuit open	History

Technician Notes

2016355293

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.