



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250602160107
Test Time: 2025-06-02 16:01:07
Technician: Andrick

Mitsubishi VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mitsubishi/ASX/--
VIN: JMYXTGA2WFZC00865

Odometer Reading: 83242
License Plate: HZD020MP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System	Status/DTC
MPI/GDI/Diesel	 0
AT/CVT/A-MT/TC-SST	 0
ABS/ASC/ASTC/WSS - A.S.C.	 0
SRS-Air Bag	 2
Meter	 0
Air Conditioner	 0
Auto Cruise	  0
4WS/Electric Power Steering	 0
Steering Angle Sensor	 0
KOS/IMMO/Keyless/TPMS - IMMOBI & KOS	 0
AFS/ACL/Leveling	  0
OSS	 0
Corner Sensor/Back Sensor	 0
ETACS - Selection 102	 0
LIN - Selection 102	 1

DTC (3)

SRS-Air Bag (2 DTCs)

DTC	Description	Status
B1477	IG1(B) voltage extraordinary low	Stored DTC
B1476	IG1(A) voltage extraordinary low	Stored DTC



LIN - Selection 102 (1 DTC)

DTC	Description	Status
L0432	RLS RS adaptation error	Stored DTC

Technician Notes
2016899701

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.